

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'ed | Status                                                          |
|------|-------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 04 May 2020 |               | 04 May 2020 13:39<br><a href="#">Edit Adj Rpt</a> | <b>S\$5,250.00</b><br><a href="#">Edit Estimates</a> | <b>S\$5,250.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                          | Reference                                                                                                                             | Claim Details          | Documents                                                                   | <a href="#">Show All</a> |                |                    |                     |                   |              |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|------------------------|-----------------------------------------------------------------------------|--------------------------|----------------|--------------------|---------------------|-------------------|--------------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                                                                |                                                                                                                                       |                        | <b>[Created by insurer]</b>                                                 |                          |                |                    |                     |                   |              |
| Insured:                                                                                                                                                                      | <b>LION CITY RENTALS PTE LTD</b> , Co. Reg. No.: 201504621K                                                                           |                        |                                                                             |                          |                |                    |                     |                   |              |
| Main Claimant:                                                                                                                                                                | <b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K                                                                          |                        |                                                                             |                          |                |                    |                     |                   |              |
| Vehicle Reg. No.:                                                                                                                                                             | <b>SHD380L</b>                                                                                                                        | Date of Loss:          | 29/04/2020 14:00 - :59<br>[49 Months and 7 Days From LTA Reg Date (Man Yr)] |                          |                |                    |                     |                   |              |
| Claim Type:                                                                                                                                                                   | <b>TP / M2002590</b>                                                                                                                  | Policy/Cover Note No.: | ML000134 (Third Party Only)<br>Coverage: 25/02/2020 - 24/02/2021            |                          |                |                    |                     |                   |              |
| Vehicle Reg. No. (Insured):                                                                                                                                                   | <b>SLE3667M</b>                                                                                                                       | Policy No. (Claimant): |                                                                             |                          |                |                    |                     |                   |              |
|                                                                                                                                                                               |                                                                                                                                       | Excess:                | S\$1,600.00                                                                 |                          |                |                    |                     |                   |              |
| Repairer:                                                                                                                                                                     | <b>Trans-Cab Services Pte Ltd (HQ)</b> 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666                                      |                        |                                                                             |                          |                |                    |                     |                   |              |
| Handling Insurer:                                                                                                                                                             | <b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Telma Gomez</b> - 65926402]                      |                        |                                                                             |                          |                |                    |                     |                   |              |
| Adjuster:                                                                                                                                                                     | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 14/05/2020]</b> |                        |                                                                             |                          |                |                    |                     |                   |              |
| Driver/Custodian (Insured):                                                                                                                                                   | ANG LI WEN DORIS (43) , Tel: +6591447332 Email:                                                                                       |                        |                                                                             |                          |                |                    |                     |                   |              |
| Adj Asg. Remarks:                                                                                                                                                             | OI HAS NOT RPT THE ACCIDETN.                                                                                                          |                        |                                                                             |                          |                |                    |                     |                   |              |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |                                                                                                                                       |                        |                                                                             |                          |                |                    |                     |                   |              |
| There are no mail for this case.                                                                                                                                              |                                                                                                                                       |                        |                                                                             |                          |                |                    |                     |                   |              |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |                                                                                                                                       |                        |                                                                             |                          |                |                    |                     |                   |              |
| <b>Due Date</b>                                                                                                                                                               | <b>Priority</b>                                                                                                                       | <b>Type</b>            | <b>Task Group</b>                                                           | <b>Subject</b>           | <b>Handler</b> | <b>Assigned By</b> | <b>Completed On</b> | <b>Created On</b> | <b>Done?</b> |
| No results.                                                                                                                                                                   |                                                                                                                                       |                        |                                                                             |                          |                |                    |                     |                   |              |



## Claim Documents

**\*SHD380L (M2002590)**  
**[SLE3667M]**  
**TP**  
**TRANS-CAB SERVICES PTE LTD**  
**Apr 29 2020 2:00PM**  
**[LION CITY RENTALS PTE LTD]**  
**Trans-Cab Services Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

| Assessment Reports |                 |                                                                                               |  |                          | 1 per page                          | <input checked="" type="checkbox"/> |
|--------------------|-----------------|-----------------------------------------------------------------------------------------------|--|--------------------------|-------------------------------------|-------------------------------------|
| No                 | Finalized On    | Tokio Marine Insurance Singapore Ltd (HQ)                                                     |  | Thumbnail                | Print                               |                                     |
| 1                  | 18/05/20 09:00  | <b>Accident Statement</b><br>From:SC - Reg. No: SLE3667M, Claimant: LION CITY RENTALS PTE LTD |  | <a href="#">Load HTM</a> |                                     |                                     |
| Photos/Images      |                 |                                                                                               |  |                          | 3 per page                          | <input checked="" type="checkbox"/> |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                                             |  | Thumbnail                | Print                               |                                     |
| 1                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 2                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 3                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 4                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 5                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 6                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 7                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 8                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 9                  | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 10                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 11                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 12                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 13                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 14                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 15                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 16                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 17                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 18                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 19                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 20                 | 29/05/20 10:55  | <b>General View</b>                                                                           |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 21                 | 29/05/20 11:34  | <b>Reinspection Photo</b>                                                                     |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 22                 | 29/05/20 11:34  | <b>Reinspection Photo</b>                                                                     |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| 23                 | 29/05/20 11:34  | <b>Reinspection Photo</b>                                                                     |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |                                     |
| Documentation      |                 |                                                                                               |  |                          | 1 per page                          | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | Tokio Marine Insurance Singapore Ltd (HQ)                                                     |  | Thumbnail                | Print                               |                                     |
| 1                  | 04/05/20 10:35  | <b>TP - SHD380L INCOMPLETE SAS</b>                                                            |  | <a href="#">Load PDF</a> |                                     |                                     |
| 2                  | 04/05/20 10:35  | <b>MARKED ESTIMATE</b>                                                                        |  | <a href="#">Load PDF</a> |                                     |                                     |
| 3                  | 04/05/20 10:35  | <b>PRELIM</b>                                                                                 |  | <a href="#">Load PDF</a> |                                     |                                     |
| 4                  | 18/05/20 09:02  | <b>TP SHD380L SAS</b>                                                                         |  | <a href="#">Load PDF</a> |                                     |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI20005505/KTF3S2**Date:** 03/06/2020**REFERENCE**

|                              |                                      |                             |          |
|------------------------------|--------------------------------------|-----------------------------|----------|
| Handling Insurer:            | Tokio Marine Insurance Singapore Ltd | Policy No:                  | ML000134 |
| <b>Claimant Vehicle No :</b> | SHD380L                              | <b>Insured Vehicle No :</b> | SLE3667M |
| Date of Loss:                | 29/04/2020                           | Nature of Claim:            | TP       |
|                              |                                      | Claim No:                   | M2002590 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                             |             |                   |
|-----------------------------|---------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHD380L</b>                              |             |                   |
| Make & Model:               | RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) | Engine No:  | M9R8839C003007    |
| Reg. Date:                  | 22/03/2016 (Man. Year: 2015)                | Chassis No: | VF1ABL15AUC282609 |
| Colour:                     | Metallic White/Red                          | Odometer:   | 447126 km         |
| Engine Capacity:            | 1995 cc                                     |             |                   |
| Market Value/New Car Price: | N/A                                         |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>           |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |             |                  |            |
|-------------------|-------------|------------------|------------|
| Front Tyre Size:  | 215/60 R16  | Rear Tyre Size:  | 215/60 R16 |
| Front Left Side:  | Sailun 9 mm | Rear Left Side:  | Giti 8 mm  |
| Front Right Side: | Sailun 9 mm | Rear Right Side: | Giti 8 mm  |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 19,131.58         | 5,452.81          | 13,678.77         | 71.50         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 18,660.00         | 1,520.00          | 17,140.00         | 91.85         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>37,791.58</b>  | <b>6,972.81</b>   | <b>30,818.77</b>  | <b>81.55</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>5,250.00</b>   |                   |               |
| <b>(S\$)</b>                             | 37,791.58         | 5,250.00          | 32,541.58         | 86.11         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 2,645.41          | 367.50            | 2,277.91          | 86.11         |
| <b>Nett Amount (S\$)</b>                 | <b>40,436.99</b>  | <b>5,617.50</b>   | <b>34,819.49</b>  | <b>86.11</b>  |

**INSPECTION**

|                             |            |               |                                                                               |
|-----------------------------|------------|---------------|-------------------------------------------------------------------------------|
| Date of Assignment:         | 04/05/2020 |               |                                                                               |
| Date Inspected:             | 30/04/2020 | Inspected At: | Trans-Cab Services Pte Ltd (HQ)<br>2 Ang Mo Kio Street 63<br>Singapore 569111 |
| Estimated Period of Repair: | 5.0 days   |               |                                                                               |

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 03 Jun 2020)

**Parts:** 143    RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHD380L)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

| No. | Qty | Part No. Particulars                     | Condition     | Repairer's  | Reference | Amount       |
|-----|-----|------------------------------------------|---------------|-------------|-----------|--------------|
| 1   | 1   | *BUMPER COVER REAR                       | Buckled       | 561.70 FL   | -         | *561.70 FL   |
| 2   | 1   | *BUMPER LOWER REAR                       | Dented / Cut  | 411.90 FL   | -         | *411.90 FL   |
| 3   | 1   | *BUMPER BRACKET CTR REAR                 | Distorted     | 98.10 FL    | -         | *98.10 FL    |
| 4   | 1   | *BUMPER BRACKET SIDE RH REAR             | Serviceable   | 82.10 FL    | -         | *- FL        |
| 5   | 1   | *BUMPER RETAINER RH REAR                 | Serviceable   | 59.80 FL    | -         | *- FL        |
| 6   | 1   | *BUMPER REFLECTOR RH                     | Serviceable   | 16.60 FL    | -         | *- FL        |
| 7   | 1   | *BUMPER BRACKET SIDE LH REAR             | Serviceable   | 80.80 FL    | -         | *- FL        |
| 8   | 1   | *BUMPER RETAINER LH REAR                 | Serviceable   | 54.20 FL    | -         | *- FL        |
| 9   | 1   | *BUMPER REFLECTOR LH                     | Serviceable   | 16.60 FL    | -         | *- FL        |
| 10  | 1   | *BUMPER BEAM REAR                        | Bent          | 547.80 FL   | -         | *547.80 FL   |
| 11  | 1   | *BUMPER BEAM BRACKET LH REAR             | Repair        | 114.50 FL   | -         | *- FL        |
| 12  | 1   | *BUMPER BEAM BRACKET RH REAR             | Repair        | 100.90 FL   | -         | *- FL        |
| 13  | 1   | *BUMPER HARNESS REAR                     | Serviceable   | 301.10 FL   | -         | *- FL        |
| 14  | 1   | *BOOT REAR                               | Bent          | 1,677.20 FL | -         | *1,677.20 FL |
| 15  | 1   | *BOOT FINISHER                           | Serviceable   | 344.70 FL   | -         | *- FL        |
| 16  | 1   | *BOOT REFLECTOR LAMP LH                  | Serviceable   | 277.70 FL   | -         | *- FL        |
| 17  | 1   | *BOOT REFLECTOR LAMP RH                  | Cracked       | 277.70 FL   | -         | *277.70 FL   |
| 18  | 1   | *BOOT BADGE RENAULT                      | Necessary     | 82.40 FL    | -         | *82.40 FL    |
| 19  | 1   | *BOOT BADGE                              | Necessary     | 95.80 FL    | -         | *95.80 FL    |
| 20  | 1   | *BOOT STRUT LH                           | Serviceable   | 145.10 FL   | -         | *- FL        |
| 21  | 1   | *BOOT STRUT RH                           | Serviceable   | 145.10 FL   | -         | *- FL        |
| 22  | 1   | *BOOT HINGE LH                           | Repair        | 254.20 FL   | -         | *- FL        |
| 23  | 1   | *BOOT HINGE RH                           | Repair        | 253.80 FL   | -         | *- FL        |
| 24  | 1   | *BOOT TRIM BOARD                         | Serviceable   | 611.00 FL   | -         | *- FL        |
| 25  | 1   | *BOOT LOCK                               | Repair        | 246.60 FL   | -         | *- FL        |
| 26  | 2   | *BOOT RUBBER PLUG                        | Serviceable   | 139.30 FL   | -         | *- FL        |
| 27  | 1   | *BOOT SWITCH                             | Serviceable   | 113.00 FL   | -         | *- FL        |
| 28  | 1   | *BOOT LOCK LINKAGE HOLDER                | Serviceable   | 99.50 FL    | -         | *- FL        |
| 29  | 2   | *LICENCE PLATE LAMP                      | Serviceable   | 26.30 FL    | -         | *- FL        |
| 30  | 1   | *TAILLAMP RH                             | Mtg Cracked   | 313.10 FL   | -         | *313.10 FL   |
| 31  | 1   | *TAILLAMP PANEL RH                       | Repair        | 401.40 FL   | -         | *- FL        |
| 32  | 1   | *TAILLAMP LH                             | Mtg Cracked   | 401.40 FL   | -         | *401.40 FL   |
| 33  | 1   | *TAILLAMP PANEL LH                       | Repair        | 401.40 FL   | -         | *- FL        |
| 34  | 1   | *OUTER PANEL REAR (END PANEL)            | Bent          | 745.80 FL   | -         | *745.80 FL   |
| 35  | 1   | *OUTER PANEL REAR (END PANEL) TRIM       | Dented        | 404.56 FL   | -         | *404.56 FL   |
| 36  | 1   | *SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) | Repair        | 1,229.40 FL | -         | *- FL        |
| 37  | 1   | *SPARE WHEEL PANEL TRIM                  | Serviceable   | 612.21 FL   | -         | *- FL        |
| 38  | 1   | *SPARE TYRE BOARD                        | Serviceable   | 680.90 FL   | -         | *- FL        |
| 39  | 1   | *EXHAUST REAR                            | Repair        | 5,263.60 FL | -         | *- FL        |
| 40  | 1   | *EXHAUST CAP REAR                        | Repair        | 125.40 FL   | -         | *- FL        |
| 41  | 1   | *SET PARKING AID                         | Serviceable   | 700.00 FS   | -         | *- FS        |
| 42  | 1   | *SET REAR BUMPER CLIP                    | Necessary     | 69.00 FS    | -         | *69.00 FS    |
| 43  | 1   | *SET BUMPER BRACKET CTR CLIP             | Necessary     | 33.00 FS    | -         | *33.00 FS    |
| 44  | 1   | *SET BUMPER BRACKET SIDE CLIP RH RR      | Not Necessary | 20.00 FS    | -         | *- FS        |
| 45  | 1   | *SET BUMPER RETAINER RH CLIP RR          | Not Necessary | 25.00 FS    | -         | *- FS        |
| 46  | 1   | *SET BUMPER BRACKET SIDE CLIP LH RR      | Not Necessary | 20.00 FS    | -         | *- FS        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. Particulars                     | Condition     | Repairer's | Reference | Amount    |
|-----|-----|------------------------------------------|---------------|------------|-----------|-----------|
| 47  | 1   | *SET BUMPER RETAINER CLIP LH RR          | Not Necessary | 25.00 FS   | -         | *- FS     |
| 48  | 1   | *SET BUMPER LOWER REAR RIVET             | Not Necessary | 30.00 FS   | -         | *- FS     |
| 49  | 1   | *SET BUMPER LOWER REAR CLIP              | Necessary     | 66.00 FS   | -         | *66.00 FS |
| 50  | 2   | *END PANEL SEAM SEALANT                  | Not Necessary | 170.00 FS  | -         | *- FS     |
| 51  | 1   | *SET BOOT STICKER TRANS-CAB              | Necessary     | 35.00 FS   | -         | *30.00 FS |
| 52  | 1   | *BOOT STICKER 6555-3333                  | Necessary     | 35.00 FS   | -         | *30.00 FS |
| 53  | 1   | *BOOT INNER TRIM CLIP                    | Not Necessary | 45.00 FS   | -         | *- FS     |
| 54  | 1   | *BOOT WEATHERSTRIP (@ \$178.20 DISC 50%) | Cut           | 160.38 FS  | -         | *89.10 FS |
| 55  | 1   | *SPARE TYRE RIM (ROUE 7J 16H 2547)       | Serviceable   | 385.00 FS  | -         | *- FS     |
| 56  | 1   | *SPARE TYRE                              | Serviceable   | 330.00 FS  | -         | *- FS     |
| 57  | 1   | *TAILLAMP CLIP RH                        | Necessary     | 25.00 FS   | -         | *25.00 FS |
| 58  | 2   | *REAR WINDSCREEN SEALANT                 | Not Necessary | 150.00 FS  | -         | *- FS     |
| 59  | 1   | *WINDSCREEN MOULDING                     | Not Necessary | 180.00 FS  | -         | *- FS     |
| 60  | 1   | *REAR WINDSCREEN INNER SPONGE SEAL       | Not Necessary | 120.00 FS  | -         | *- FS     |
| 61  | 1   | *TAILLAMP CLIP LH                        | Necessary     | 25.00 FS   | -         | *25.00 FS |
| 62  | 1   | *REAR BUMPER PROTECTOR                   | Necessary     | 120.00 FS  | -         | *30.00 FS |
| 63  | 1   | *SET REAR LICENCE PLATE WITH HOLDER      | Serviceable   | 100.00 FS  | -         | *- FS     |
| 64  | 1   | *SET END PANEL INSULATION PAD            | Serviceable   | 200.00 FS  | -         | *- FS     |
| 65  | 1   | *SET BOOT FINISHER CLIP                  | Not Necessary | 30.00 FS   | -         | *- FS     |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>20,913.05</b> | <b>6,014.56</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 1,781.47         | 561.75          |
| <b>Total Parts (\$\$)</b>                                  | <b>19,131.58</b> | <b>5,452.81</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                | Lab.Type | Repairer's       | Amount          |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                            |          |                  |                 |
| 1                               | TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.                                                        | New      | 170.00           | 0.00            |
| 2                               | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. | New      | 7,500.00         | 600.00          |
| 3                               | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.                                                           | New      | 380.00           | 0.00            |
| 4                               | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                               | New      | 380.00           | 0.00            |
| 5                               | TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                | New      | 170.00           | 60.00           |
| 6                               | TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                         | New      | 380.00           | 60.00           |
| 7                               | TO REPAIR AND REALIGN REAR EXHAUST PIPE.                                                                                   | New      | 350.00           | 0.00            |
| 8                               | TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                            | New      | 170.00           | 0.00            |
| 9                               | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                   | New      | 220.00           | 0.00            |
| 10                              | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                    | New      | 170.00           | 60.00           |
| 11                              | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                          | New      | 7,500.00         | 660.00          |
| 12                              | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.                                            | New      | 380.00           | 0.00            |
| 13                              | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.                                                                           | New      | 170.00           | 0.00            |
| 14                              | TO REINSTALL REAR BUMPER PARKING SENSOR.                                                                                   | New      | 170.00           | 60.00           |
| 15                              | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                    | New      | 170.00           | 20.00           |
| 16                              | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.                            | New      | 380.00           | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                            |          | <b>18,660.00</b> | <b>1,520.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >