



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre  
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721  
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

CHYE THIAM MAINTENANCE PTE LTD  
14 TAMPINES INDUSTRIAL DRIVE  
SINGAPORE 528530

Estimate : ES006987

Attention : THE OWNER  
Contact : 64819588 83518839

Date : 29/04/2020  
Vehicle Num. : YN5735K  
Make/Model : MITSUBISHI CANTER-2013  
Chassis/Eng# : FEB71GA00011/4P10A90394  
Accident Date : 29/04/2020  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|                       |   |                                  |  |  |
|-----------------------|---|----------------------------------|--|--|
| NETT ITEMS :          |   |                                  |  |  |
| 1.                    | 1 | FRONT W/SCREEN                   |  |  |
| 2.                    | 1 | FRONT W/SCREEN RUBBER SEAL       |  |  |
| 3.                    | 1 | FRONT MIRROR STAY R/H            |  |  |
| 4.                    | 1 | SIDE MIRROR R/H                  |  |  |
| 5.                    | 1 | FRONT DOOR R/H                   |  |  |
| 6.                    | 1 | FRONT DOOR OUTER STRIP R/H       |  |  |
| 7.                    | 1 | FRONT DOOR GLASS R/H             |  |  |
| 8.                    | 1 | FRONT SIGNAL LAMP R/H            |  |  |
| 9.                    | 1 | FRONT BUMPER                     |  |  |
| 10.                   | 1 | FRONT SIDE BOARD R/H             |  |  |
| 11.                   | 1 | FRONT SIDE BOARD R/H RAILING     |  |  |
| 12.                   | 4 | FRONT SIDE BOARD R/H HINGES      |  |  |
| 13.                   | 1 | FRONT SIDE BOARD R/H SAFETY LOCK |  |  |
| 14.                   | 1 | REAR SIDE BOARD R/H              |  |  |
| 15.                   | 1 | REAR SIDE BOARD R/H SAFETY LOCK  |  |  |
| 16.                   | 4 | REAR SIDE BOARD R/H HINGES       |  |  |
| 17.                   | 1 | TAIL BOARD                       |  |  |
| 18.                   | 1 | TAIL BOARD SAFETY LOCK R/H       |  |  |
| 19.                   | 1 | REAR FLOOR BOARD                 |  |  |
| 20.                   | 2 | REAR CROSS MEMBER BAR            |  |  |
| 21.                   | 1 | REAR END PANEL R/H               |  |  |
| Nett Total S\$ :      |   |                                  |  |  |
| 10.00% Discount S\$ : |   |                                  |  |  |
| SPECIAL NETT ITEMS :  |   |                                  |  |  |
| 1.                    | 1 | ERP BRACKET                      |  |  |

CRA ✓ 1,456.30  
 net ✓ 451.50  
 R/R 375.60  
 M/S ✓ 165.00  
 R/R 1,965.20  
 cut ✓ 354.70  
 net X 685.90  
 cut ✓ 266.36  
 cut ✓ 795.60  
 did ✓ 885.20  
 bt ✓ 580.00  
 168.20 RX 672.80  
 bt ✓ 296.40  
 bt ✓ 1,885.20  
 bt ✓ 296.40  
 168.20 bt 672.80  
 bt ✓ 1,769.20  
 bt ✓ 296.40  
 cut ✓ 7,569.00  
 380.00 1,140.00  
 bt ✓ 375.10  
 20255.16  
 18229.64  
 23,954.66  
 2,395.47  
 21,559.19  
 net ✓ 38.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

CHYE THIAM MAINTENANCE PTE LTD  
14 TAMPINES INDUSTRIAL DRIVE  
SINGAPORE 528530

Attention : THE OWNER  
Contact : 64819588 83518839

Estimate : ES006987

Date : 29/04/2020  
Vehicle Num. : YN5735K  
Make/Model : MITSUBISHI CANTER-2013  
Chassis/Eng# : FEB71GA00011/4P10A90394  
Accident Date : 29/04/2020  
Claim No. :  
Reference :  
Policy No. :

| S/N                                                                                                                                                                     | Quantity | Particular                               | Unit Price   | Amount S\$ |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------------------------------|--------------|------------|
| 2.                                                                                                                                                                      | 1        | DOOR STICKER BLACK <i>company</i>        | <i>net</i> ✓ | 25.00      |
| 3.                                                                                                                                                                      | 1        | FRONT DOOR COMPANY LETTERING STICKER R/H | <i>net</i> ✓ | 65.00      |
| 4.                                                                                                                                                                      | 1        | FRONT SIDE BOARD R/H ALUMINIUM PLATE     | <i>bt</i> ✓  | 480.00     |
| 5.                                                                                                                                                                      | 1        | FRONT SIDE BOARD R/H COMPANY STICKER     | <i>net</i> ✓ | 65.00      |
| 6.                                                                                                                                                                      | 1        | REAR SIDE BOARD R/H ALUMINIUM PLATE      | <i>bt</i> ✓  | 480.00     |
| 7.                                                                                                                                                                      | 1        | REAR SIDE BOARD R/H WOODEN PLANK         | <i>cur</i> ✓ | 650.20     |
| 8.                                                                                                                                                                      | 1        | TAIL BOARD CUSTOMIZE ALUMINIUM PLATE     | <i>bt</i> ✓  | 480.00     |
| 9.                                                                                                                                                                      | 1        | 8 PAX STICKER                            | <i>net</i> ✓ | 15.00      |
| 10.                                                                                                                                                                     | 1        | 60 KM/H STICKER                          | <i>net</i> ✓ | 15.00      |
| 11.                                                                                                                                                                     | 1        | REAR FLOOR ALUMINUM PLATE                | <i>bt</i> ✓  | 850.00     |
| Special Nett Total S\$ :                                                                                                                                                |          |                                          | 3163.20      | 3,163.20   |
| LABOUR :                                                                                                                                                                |          |                                          |              |            |
| TO SUPPLY AND INSTALL REAR CUSTOMIZE CANOPY                                                                                                                             |          |                                          | 1200         | 1,850.00   |
| REMOVE & INSTALL FRONT W/SCREEN                                                                                                                                         |          |                                          | 120          | 250.00     |
| CHECK WIRING AND LIGHTING                                                                                                                                               |          |                                          | 30           | 120.00     |
| REMOVE/REINSTALL REAR LOAD BED                                                                                                                                          |          |                                          | 500          | 750.00     |
| REMOVE & REINSTALL REAR CROSS MEMBER                                                                                                                                    |          |                                          |              | 90.00      |
| SPRAY PAINT DAMAGED AREA AFFECTED                                                                                                                                       |          |                                          | 1300         | 2,500.00   |
| RUST PROOFING TREATMENT                                                                                                                                                 |          |                                          | 100          | 180.00     |
| REMOVE & INSTALL REAR BED CUSTOMIZE ALUMINIUM PLATES OF TAIL, SIDE BOTH R/H.                                                                                            |          |                                          | 60           | 90.00      |
| TO CUT OFF REAR END PANEL. REAR BED MEMBER, REAR BED UNDER CROSS MEMBER FRAMES, KNOCK AND STRAIGHTEN REAR BED FLOOR PANEL, CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS |          |                                          | 1800         | 3,900.00   |
| Labour Total S\$ :                                                                                                                                                      |          |                                          | 5110.        | 9,730.00   |

SingDollars : Thirty-Four Thousand Four Hundred Fifty-Two & Cents Thirty-Nine Only

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

18229.64

3163.20

5110

26502.84

Total S\$ : 34,452.39

Tauflin 97495749

4/5/20 @ 1030

-wp-

\*To check repair limit-

lumpsum

Resumy after repair

13 days

tauflin@lkkanto.com

20% - 21202.27

Repair limit \$14,000

4/5/14000.



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre  
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721  
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

CHYE THIAM MAINTENANCE PTE LTD  
14 TAMPINES INDUSTRIAL DRIVE  
SINGAPORE 528530

Attention : THE OWNER  
Contact : 64819588 83518839

Estimate : ES006988

Date : 29/04/2020  
Vehicle Num. : YN5735K  
Make/Model : MITSUBISHI CANTER-2013  
Chassis/Eng# : FEB71GA00011/4P10A90394  
Accident Date : 29/04/2020  
Claim No. :  
Reference :  
Policy No. :

| S N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|    |  |                                        |  |  |
|----|--|----------------------------------------|--|--|
| 1. |  | LIST ITEMS :                           |  |  |
| 2. |  | TRUCK MONTED ATTENUATOR 350DX ENERGY   |  |  |
| 3. |  | ABSORPTION SYSTEM ( MEET NCHRP 350 TL2 |  |  |
|    |  | CRITERIA ) C/W HYDRAULIC LIFT UP       |  |  |

List Total S\$ :

LABOUR :  
CHANGE TAIL LAMP AND CHECK WIRING  
LABOUR CHARGE TO REMOVE AND INSTALL TMA  
TO SUPPLY AND CHANGE REFLECTIVE STICKERS

Labour Total S\$ :

42,000.00

42,000.00

250.00

3,000.00

1,600.00

4,850.00

\$14000

\$26600

15 \$40,600 18 days

Taufik 97495749

WP 4/5/20 @ 1630

33260

1/5 @ 26,600

Lumpsum

Resurvey after repair

05 days

taufik @ lkkauto.com

SingDollars : Forty-Six Thousand Eight Hundred Fifty Only

Total S\$ : 46,850.00

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: