

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
UNITED OVERSEAS INSURANCE LTD Re			Ref : CS/UOI20005525/Kqf3e2		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date: 21-05-2020 Code: UOI2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLR 1053D	Veh. Inspected	SLU 2082Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	SLR 1053D	Excess (\$)	0.00	
	Assign From	JOSEPHINE WONG	Assign Date	04/05/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	KMHD841CMJU570467	Colour	METALLIC SILVER	
	Odometer	21477	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	NEXEN	8 mm	
	L/H Front Tyre	195/65 R15	NEXEN	8 mm	
	R/H Rear Tyre	195/65 R15	NEXEN	8 mm	
	L/H Rear Tyre	195/65 R15	NEXEN	8 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/04/2020	Inspection Date	04/05/2020	
	Survey held at	at 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY			
	Repairer	R C AUTO			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				