



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

20th May 2020

Ref: SHC1690R

Our Ref: TPC/GBE7740B/T0777

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road
#16-01 City House
Singapore 068877

Dear Sir/Mdm,

**ACCIDENT BETWEEN GBE7740B AND SHC1690R ALONG BLK 65A / 66
GEYLANG BAHRU DATE 30/04/2020 @16:30HRS.**

We are the repairer of motor vehicle no. **GBE7740B** which was involved in the above accident.

Our investigation reveals that the owner of motor vehicle No. **SHC1690R** is insured with your organization at the time of the accident. Owner of vehicle No. **GBE7740B** sustained damages and the owner is now claiming the following cost of repairs and other consequential loss suffered as itemized below:-

1) Cost of Repair (TI062699)	S\$ 5,885.00 nett
2) LOU (DI601160)	S\$ 560.00 nett
3) Search Fee (TP107670)	S\$ 7.49 nett

Total Amount	S\$ 6,452.49 nett
--------------	--------------------------

Enclosed all the above supporting documents and Letter of Authorization to Act cum Discharge Voucher and Letter of Authority for Third Party claims.


Your prompt attention and settlement of the above claim would be very much appreciated.

Thank you.

Yours sincerely



Janet Lim
Falcon-Air Auto Services Pte Ltd
Email Add: janet@falconair.com.sg
(Tampines Branch)



FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

**FALCON-AIR**

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Tax Invoice : TI062699

Date : 20/05/2020

Vehicle Num. : GBE 7740B

Make/Model : TOYOTA HIACE

Chassis/Eng# : JTFHT02P400189604

Accident Date : 30/04/2020

Claim No. :

Reference :

Policy No. :

Amount S\$

BEING LUMP SUM REPAIR
(Inclusive of Parts, panel beating, labour
and spray painting)


5,500.00

E. & Total S\$: 5,500.00

GST 7% S\$: 385.00

Amount Due S\$: 5,885.00

=====


for FALCON AIR AUTO SERVICES PTE LTD

(TAMPINES BRANCH)

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg

**FALCON-AIR AUTO SERVICES PTE LTD**

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE SINGAPORE 068877

Attention : Motor Claim Department
Contact : 62222311 Fax No. : 62223547

Disbursement : DI601160

Date : 20/05/2020
Vehicle Num. : GBE 7740B
Make/Model : TOYOTA HIACE
Chassis/Eng# : JTFHT02P400189604
Accident Date : 30/04/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		BEING LOSS OF USAGE FOR 7 days @80pd (include Weekend and Public Holiday)		560.00

E. & O.E.	Total S\$:	560.00
		=====

for FALCON AIR AUTO SERVICES PTE LTD

(TAMPINES BRANCH)

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg



FALCON-AIR
CASH

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Tax Invoice : TP107670

Invoice Date : 04/05/2020
Vehicle Num. : GBE 7740B
Make/Model : TOYOTA HIACE
Mileage(Km) :
POWVO/RO# : SHC1690R
Ref./Remark : SEARCH FEE

S/N	Quantity	Particular	Unit Price	Amount S\$
		BEING SEARCH FEE FOR VEHICLE SHC1690R DOA 30/04/2020 @16:30 MS FIRST CAPITAL INSURANCE LIMITED		7.00

SingDollars : Seven & Cents Forty-Nine Only

E. & O.E.	Total S\$:	7.00
	GST 7% S\$:	0.49
	Amount Due S\$:	7.49

=====

Terms : Cash

Customer's Signature/Co. Stamp

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 04 May 2020 / 09:34:18

Receipt Date/Time : 04 May 2020 / 09:34:18

Tax Invoice/Receipt

Receipt No. : ITNET-00000-200504-000372

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SHC1690R				
As at 30 Apr 2020/16:30:00				
Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED				
1	Insurance Enquiry - SHC1690R Enquiry Fee 20200504093302764432	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	426588XXXXXX1141 eNETS Credit Card			7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

LETTER OF AUTHORITY

To : MOTOR CLAIMS DEPT

ACCIDENT INVOLVING GBE 7740B and SHC1690R

ON 30/04/2020 ALONG BLK 65A/66 Geylang Bahru

CO. REG NO/

I, RAM ASIA GROUP PTE LTD NRK NO. 201103875R

Of No 32 Kallang Pudding Road #04-06, Elite Ind Building 1 (349313)

Owner of Motor Vehicle Registration No.: GEB7740B do hereby authorize

M/s FALCON-AIR AUTO SERVICES PTE LTD as my agent and representative to correspond in, negotiate

And settle, on my behalf, my claim against the parties involved in the above mentioned accident. I

Also authorize the said insurers to make all payments in favor of Falcon-Air Auto Services Pte Ltd directly.



Date & Signature of Owner/Co. Stamp

A handwritten signature in black ink, consisting of a stylized 'R' followed by a cursive flourish, written over a horizontal line.

Date & Signature of Driver

"WITHOUT PREJUDICE
to any
PERSONAL INJURIES"