

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUTO	O & GENERAL IN	SURANCE (S) PL	Ref : CS/AGI20005556/F	CS/AGI20005556/Kyf3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 15-06-2020		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKV 7174P	Veh. Inspected	SMH 8267Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10006266	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	05/05/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	MR2B23F3501163980	Colour	METALLIC GREY	
	Odometer	9181	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/50 R16	BRIDGESTONE	9 mm	
	L/H Front Tyre	195/50 R16	BRIDGESTONE	9 mm	
	R/H Rear Tyre	195/50 R16	BRIDGESTONE	9 mm	
	L/H Rear Tyre	195/50 R16	BRIDGESTONE	9 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	02/05/2020	Inspection Date	05/05/2020	
	Survey held at KUM CHEW MOTOR WORKSHOP				
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: