

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6942 G

1 pc	Front bumper centre grille X	\$	174.00
1 pc	Front bumper CRA	\$	531.00 ✓
1 pc	Front bumper emblem nec	\$	44.00 ✓
1 pc	Front o/s head lamp XUN	\$	1,028.00
1 pc	Front bumper o/s side retainer nec	\$	16.00 ✓
1 pc	Front o/s wheel cover cut	\$	116.00 ✓
1 pc	Front bumper o/s protector XUN	\$	51.00
1 pc	Front bumper o/s fog lamp cover XUN	\$	66.00
1 pc	Front o/s fender X(R)	\$	384.00
1 pc	Front o/s fender inner shield CUT	\$	120.00 ✓
	Front grille Br	\$	2,530.00 \$827
		Less 10%	\$ 253.00 \$744.3
			\$ 2,277.00

1 pc	Front bumper clips <i>nec</i>	\$	48.00
1 pc	Front o/s fender sticker <i>xnn</i>	\$	30.00
1 set	Front o/s fender inner shield clips <i>nec</i>	\$	28.00 <i>\$76</i>
	To check front o/s wheel alignment	\$	80.00 <i>xnn</i>
	Sundry	\$	50.00 <i>\$30</i>
	To adjust/focus front o/s head lamp	\$	30.00 <i>xnn</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	800.00 <i>\$360</i>
	To putty and spray painting on front bumper, front o/s fender, bonnet grille, o/s mirror cover <i>days</i>	\$	800.00 <i>\$480</i>
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 <i>\$50</i>
		\$	4,263.00

LKK Auto Consultants hence notify

4/5: \$ $\overline{1650} = \underline{2}$ repair days

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-May-20

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6942 G

1 pc

Bonnet grille *Br*

\$ 385.00

Less 10%

\$ 38.50

\$ 346.50