

## Sherwin Beh (LKK Auto)

---

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** 28 April 2020 12:21  
**To:** Sherwin Beh (LKK Auto); Naz (LKKAuto)  
**Cc:** Bryan Ang (LKKAuto); Beifeng NG (SPF); Mohammed Feroz HUSSIEN (SPF); Mohamed Yazid MOHAMMED YUSOFF (SPF); Raziz TAHAR (SPF); Adrian LIM (SPF)  
**Subject:** Mechanical Inspection Report Request

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **16 vehicles** below: **[The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]**

- a) **Case IAFP-IB-20200427 - Mechanical Inspection of Motorcycle, FZ4415C (TP/IP/19835/2020)**
- b) **Case IAFP-IB-20200427 - Mechanical Inspection of Motor Car, SLE6404K (TP/IP/19835/2020)**

On 16 April 2020 sometime before 4.45 p.m., the motorcyclist (A1) was travelling CTE towards AYE on lane 4 of a 6 lane road and at the same time, the motor car (B1) was travelling along PIE slip road into CTE towards Aye, on lane 5 of a 6 lanes road. When B1 reached the tip of the road divider, B1 made a lane change to his right where A1 was at B1's right side. As such, B1's right rear portion collided onto A1's left. The impact caused A1 to skidded and fall on lane 3. A1 continued to skid a short distance and landed between lane 2 and lane 3. Due to the impact, rider was conveyed in an unconscious state to Khoo Teck Puat Hospital and currently in ICU for observation.

**Vehicles to be inspected:**    **FZ4415C** - Rider (Seriously Injured)  
   **SLE6404K** - Driver (Potential Defendant)

IO In-Charge: IO Ng Beifeng

- c) **Case IAFP-IB-20200427 - Mechanical Inspection of Motor Lorry, XD1936M (TP/IP/15115/2020)**

On 19 March 2020 at about 7.47 am, Police incident was created regarding an accident along Jalan Boon Lay towards Jurong Island. The motor-lorry, XD1936M, was travelling along Jurong West Avenue 4 making a right turn into Jalan Boon Lay. Upon completion of the right turn, the motor-lorry was travelling straight on the center lane of 3 lanes road and was picking up speed to overtake a public bus which was travelling on the left lane. It was seen that the left hydraulic arm of the motor-lorry was extended out and it collided with the rear of the public bus. The hydraulic arm was not extended at all prior to the accident while the lorry was making the right turn.

**Vehicle to be inspected:**    **XD1936M** - Driver (Potential Defendant)

IO In-Charge: IO Mohd Feroz

- d) **Case IAFP-IB-20200427 - Mechanical Inspection of Motorcycle, FBL7635K (TP/IP/79475/2019)**
- e) **Case IAFP-IB-20200427 - Mechanical Inspection of Motor Car, SJV3951B (TP/IP/79475/2019)**

On 26 December 2019 sometime before 2.06 a.m., the accused was driving his motor car on lane 1 of 3-lanes along SLE(BKE) near to 11.5KM mark when he collided into the rear of the motorcycle which was ridden by the Deceased. Deceased was conveyed to KTPH where he succumbed to his injuries and was pronounced dead on the same day at 3.15am.

**Vehicles to be inspected:**    **FBL7635K** - Rider (Deceased)  
   **SJV3951B** - Driver (Potential Defendant)

IO In-Charge: SIO Adrian Lim

**f) Case IAFP-IB-20200427 - Mechanical Inspection of Motor Taxi, SHC1824Y (TP/IP/73827/2019)**

On 27 November 2019 (Wednesday) at about 5.22 am, the motor taxi, SHC 1824 Y, was travelling along Bukit Batok East Avenue 6 when at the junction of Avenue 3 collided with a pedestrian who was crossing from the taxi's right to left. The pedestrian was sent to NUH where he was pronounced dead 3 days later.

**Vehicle to be inspected:**    **SHC1824Y** - Driver (Potential Defendant)

IO In-Charge: SIO Yazid

**g) Case IAFP-IB-20200427 - Mechanical Inspection of Motorcycle, FP8084A (TP/IP/19051/2020)**

**h) Case IAFP-IB-20200427 - Mechanical Inspection of Motor Car, SMH6769E (TP/IP/19051/2020)**

On 12 April 2020 Friday at 3.04 p.m., the Deceased (who was alone on his motorcycle FP 8084 A) was travelling along Dunearn Road towards Bukit Timah Road on lane 3 of 3 lanes road when motorcar SMH 6769 E driven by the Involved Party who was travelling on lane 1 of 3 lanes road made a lane change to lane 3 and encroached into the travel path of the Deceased. The Deceased subsequently collided into the rear left portion of motorcar SMH 6769 E . As a result of the accident, the Deceased sustained head injuries and succumbed to his injuries. He was pronounced dead at the hospital.

**Vehicles to be inspected:**    **FP8084A** - Rider (Deceased)  
   **SMH6769E** - Driver (Potential Defendant)

IO In-Charge: SIO Raziz

**i) Case IAFP-IB-20200427 - Mechanical Inspection of Motor Taxi, FBQ9540K (TP/IP/18953/2020)**

On 9 April 2020 (Thursday) at 6.01 p.m., the Deceased (who was alone on his motorcycle) was travelling along TPE towards SLE slip road into Yio Chu Kang and believed to had self-skidded along the said location. As a result of the accident, the Deceased sustained multiple injuries and was pronounced dead at the accident scene.

**Vehicle to be inspected:**    **FBQ9540K** - Rider (Deceased)

IO In-Charge: SIO Raziz

**j) Case IAFP-IB-20200427 - Mechanical Inspection of Motor Van, GBC6370C (TP/IP/18045/2020)**

On 3 April 2020 (Friday) at 3.04 p.m., the Deceased who was a pedestrian at the time was walking across a pedestrian crossing when motor van GBC 6370 C which was travelling along Cross Street made a right

turn into Robinson Road and collided into the Deceased. As a result of the accident, the Deceased sustained head injuries and succumbed to her injuries. She was pronounced dead at the hospital..

**Vehicle to be inspected:**     **GBC6370C** - Driver (Potential Defendant)

IO In-Charge: SIO Raziz

- k) **Case IAFP-IB-20200427 - Mechanical Inspection of Motor Bus, PC6836K (TP/IP/20345/2020)**
- l) **Case IAFP-IB-20200427 - Mechanical Inspection of Motorcycle, FBN364C (TP/IP/20345/2020)**

On 21 April 2020 (Tuesday) at about 8.23 am, the deceased riding motorcycle FBN 364 C was travelling on lane 1 of 3 lanes along Old Choa Chu Kang Road when the driver of motorbus PC6836 K travelling on the same direction with the deceased on lane 2 of 3 lanes made a right turn from lane 2 into Jalan Lekar resulting in the deceased to collide onto the motor bus. The deceased was sent to Ng Teng Fong General Hospital (NTFGH) where he succumbed to his injuries and was pronounced dead on the same day at 9.49 am.

**Vehicle to be inspected:**     **PC6836K** - Driver (Potential Defendant)  
   **FBN364C** - Rider (Deceased)

IO In-Charge: SIO Yazid

- m) **Case IAFP-IB-20200427 - Mechanical Inspection of Motor Taxi, SHC7555J (TP/IP/20467/2020)**
- n) **Case IAFP-IB-20200427 - Mechanical Inspection of Motor Lorry, GBJ9489M (TP/IP/20467/2020)**

On 21 April 2020 (Tuesday) at about 8.23 am, the deceased was driving motor lorry GBJ 9489 M along Phillips Avenue and at the junction of Yio Chu Kang Road collided with a motor taxi SHC 7555 J which was travelling along Yio Chu Kang Road. As a result of the collision the motor lorry toppled to the left and the driver of the lorry was pronounced dead at the scene. **Please also assist to check if the driver and passenger of the lorry was wearing seatbelt at the time of the accident.**

**Vehicle to be inspected:**     **SHC7555J** - Driver (Involved Party)  
   **GBJ9489M** - Driver (Deceased)

IO In-Charge: SIO Yazid

- o) **Case IAFP-IB-20200427 - Mechanical Inspection of Motor Car, SLB1471P (TP/IP/21061/2020)**
- p) **Case IAFP-IB-20200427 - Mechanical Inspection of Motorcycle, WB3584Y (TP/IP/21061/2020)**

On 25 April 2020 (Saturday) at or about 6.12 a.m., the Accused was travelling on lane 2 of the 5 lanes of Eunos Link towards Hougang Avenue 3 and was intending to make a right turn into Airport Road. Upon reaching the signalised cross-junction of Eunos Link by Airport Road, the Accused made the right turn on the green only traffic light signal, resulting in a collision with the 1<sup>st</sup> Deceased, who was travelling straight from the opposite direction. Due to the collision, both Deceased persons were reported to be unconscious and were conveyed by ambulance to the Changi General Hospital. However, the 1<sup>st</sup> Deceased and 2<sup>nd</sup> Deceased succumbed to their injuries and were pronounced dead in hospital on the same day, at 6.37 a.m. and 6.59 a.m. respectively, by Dr Sim Guan Chua.

**Vehicle to be inspected:**     **SLB1471P** - Driver (Potential Defendant)  
   **WB3584Y** - Rider (Deceased)

IO In-Charge: SIO Kamaliah

2. These request has been approved by my management.

3. Thank you Sirs.

cc: IO Beifeng, IO Feroz, SIO Yazid, SIO Raziz and SIO Adrian, as requested by you.

Best regards,

Kamaliah Kamis (Miss)  
Senior Investigation Officer | Fatal Accident Investigation Team  
Traffic Police Department | Singapore Police Force  
DID: (65) 6547 6435 | FAX: (65) 6547 6352



**Singapore Police Force** – *Commemorating 200 Years of Policing*

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."