

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 9986R - AIG

Candy

Done
5/5/16

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 9986R - Candy
 VF1ABL15AUC273545
 RENAULT
 LATITUDE
 04.05.16
AIG

		PART	LIST	
1	1	BUMPER COVER FRT <i>X repair</i>	\$	968.78
2	1	BUMPER ABSORBER FRT <i>X sc</i>	\$	303.60
3	1	BUMPER BEAM FRT <i>X sc</i>	\$	703.14
4	1	BUMPER SPOILER FRT <i>X sc</i>	\$	139.81
5	1	BUMPER FOG LAMP GRILLE RH <i>X sc</i>	\$	159.40
6	1	BUMPER RETAINER FRT RH <i>X sc</i>	\$	116.47
7	1	BUMPER SUPPORT FRT RH <i>X sc</i>	\$	18.37
8	1	WIPER RESERVOIR <i>X sc</i>	\$	173.60
9	1	WIPER RESERVOIR MOTOR <i>X sc</i>	\$	91.78
10	1	HEADLAMP RH <i>✓ good</i>	\$	911.10
11	1	FENDER PANEL FRT RH <i>X repair</i>	\$	602.95
12	1	FENDER WHEELARCH FRT RH <i>X sc</i>	\$	107.33

TOTAL	\$	4,296.34
10%	\$	429.63
	\$	3,866.70

Specical Nett

1	1SET	FRONT BUMPER CLIP <i>X an</i>	\$	66.00
2	1SET	WHEELARCH CLIP RH <i>X an</i>	\$	66.00
3	1	TOW COVER FRT <i>X sc</i>	\$	14.50
4	1	CAP HUB RH FRT <i>X sc</i>	\$	35.00
5	1	RIM RH FRT <i>X sc</i>	\$	385.00
6	1	TYRE RH FRT <i>X sc</i>	\$	330.00
7	1SET	BUMPER SUPPORT FRT CLIP RH <i>X an</i>	\$	9.80
8	1SET	BUMPER RETAINER FRT CLIP RH <i>X an</i>	\$	12.50

TOTAL	\$	918.80
TOTAL PARTS	\$	4,785.50

Panel beating, knocking and straightening the
 necessary portion, remove and renewal of
 parts, adjust and realign the same

\$ *400*
 1,400.00

Candy

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63 SINGAPORE 569111
TEL NO.6287 6666 FAX NO.6257 1330
CO/GST REG NO.201019626G
SHB 9986R - AIG

To Check Electrical Lighting Concerned.

\$

~~170.00~~ 60

Putty and spray painting of the affected portion.

\$

~~1,500.00~~ 440

To check steering geometry and computer wheel alignment

\$

~~220.00~~ X 40

To transfer of tire, rim and on wheel balancing.

\$

~~170.00~~ X 40

To rust-proofing of the affected areas.

\$

~~170.00~~ X 40

TOTAL

\$

3,630.00

Over All Total

\$

8,415.50

(PARTS BY PARTS) Repair Days

5 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ka/um 16/11/14
11 5/5/16
2 Repair Days
After Repair photo