

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/AWA20005609/Eyf3e2 ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH)60 ANSON ROAD #08-01 Date: 18-05-2020 (8th FLOOR) MAPLETREE ANSON S 079914 Code: AWA 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBJ 9641P** Veh. Inspected **SGK 7247T** Policy No. AVC2SB0005121900 Coverage (\$) 0.00 0.00 Claim No. Excess (\$) **Assign From** STELLA GOH 08/05/2020 **Assign Date** 2. **Vehicle Particulars & Condition** Make & Model TOYOTA VIOS 1497 c.c **Engine No. HIDDEN** Year of Reg. 2006 MR053HY4204198383 Chassis No. Colour BLUE 121954 KM Odometer **IN ORDER** Steering **IN ORDER** Brakes Modification SPORTS RIM FAIR General **Conditions of Tyres** 3. Size Make **Balance FALKEN** 175/65 R14 4 mm R/H Front Tyre 175/65 R14 **FALKEN** L/H Front Tyre 4 mm R/H Rear Tyre 175/65 R14 **FALKEN** 4 mm 175/65 R14 **FALKEN** 4 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 01/05/2020 11/05/2020 (02:33 PM) **Accident Date** Inspect Date / Time Survey held at JEMENTAH MOTOR WORKS BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/AWA20005609/Eyf3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.