



Your Ref: SNM20D201871/PC8017U/ADELINE

Date: 23<sup>rd</sup> Jun 2020

Our Ref: CS/CTI20005614/Gyf3e2

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Dear Sir / Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO: PC 8017U  
ACCIDENT ON 05.05.2020**

**Instruction was received from Ms Adeline Chng to inspect the vehicle Reg. No. PC 8017U at the premises of M/s: Vin's Motor Pte Ltd, 160 Sin Ming Drive #03-03, Sin Ming Auto City, Singapore 575722 on 15.05.2020.**

The following information were recorded: -

<i>Registration Number</i>	: PC 8017U
<i>Make &amp; Model</i>	: Toyota Hiace Commuter GL 2.8 Auto
<i>Chassis Number</i>	: GDH2232001465
<i>Year of Registration</i>	: 2019
<i>Engine Capacity</i>	: 2754 cc
<i>Body colour</i>	: Silver

The following are our observation / comments:-

The vehicle sustained damages at the front n/s portion. (Details see photographs enclosed)

The repaired M/s Vin's Motor Pte Ltd had agreed to undertake the repair of vehicle PC 8017U at Lump Sum \$41,500.00 before excess.

Enclosed please find damaged vehicle's photos and out invoices for your necessary action.

Yours faithfully



XING GUO QIANG  
M.MATAI, AMSAE-A  
Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.