



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Without Prejudice
18/05/20, 12.00 pm
3 days

L/S

Resurvey After Spray

Steve (LKK)

Estimation

Date: 15/5/2020

Vehicle: SML7179E

Make / Model: MERCEDES BENZ CLA180

Chassis No: WDD1173422N759874

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRONT BUMPER ✓ DEF	1	\$ 1,376.00	\$ 1,376.00
2	FRONT BUMPER REINFORCEMENT × NN	1	\$ 330.00	\$ 330.00
3	FRONT BUMPER SIDE RETAINER RH ✓ BR	1	\$ 53.00	\$ 53.00
4	FRONT BUMPER LOWER LIP CHROME CENTER × NN	1	\$ 310.00	\$ 310.00
5	FRONT BUMPER LOWER LIP CHROME RH × NN		\$ 139.00	\$ 139.00
6	FRONT BUMPER SPONGE × NN	1	\$ 139.00	\$ 139.00
7	FRONT BUMPER LOWER GRILLE ✓ CUT	1	\$ 125.00	\$ 125.00
8	FRONT BUMPER SENSOR ✓ CUT	2	\$ 300.00	\$ 600.00
9	FRONT BUMPER TOW COVER × R	1	\$ 60.00	\$ 60.00
10	FRONT BUMPER LOGO ✓ NEC	1	\$ 65.00	\$ 65.00
11	FRONT BUMPER NUMBER PLATE GARNISH × NN	1	\$ 119.00	\$ 119.00
12	FRONT SUPPORT LOWER GARNISH × NN	1	\$ 178.00	\$ 178.00
13	FRONT GRILLE ✓ BR	1	\$ 248.00	\$ 248.00
14	FRONT GRILLE CHROME ✓ CUT	2	\$ 76.00	\$ 156.00
15	FRONT GRILLE OUTER GARNISH × NN	1	\$ 146.00	\$ 146.00
16	RH FRONT HEADLAMP ✓ BR	1	\$ 2,978.00	\$ 2,978.00
17	FRONT GRILLE LOGO ✓ CUT	1	\$ 142.00	\$ 142.00
18	FRONT GRILLE LOGO BASE × NN	1	\$ 76.00	\$ 76.00
				\$ 7,164.00
			Less 10%	\$ 716.40
			Total	\$ 6,447.60
	S/Nett items:			
1	FRONT NUMBER PLATE ✓ BR	1 SET	\$ 150.00	\$ 150.00
2	MISCELLANEOUS × NN	1	\$ 200.00	\$ 200.00
				\$ 350.00
	Labour to:			
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND REFIT FRONT BUMPER SENSOR	1	\$ 150.00	\$ 150.00
3	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 150.00	\$ 150.00
4	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
5	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
6	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
7	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
				\$ 2,130.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			Parts Replacement Amount	\$ 6,797.60
			Total Amount for Labour	\$ 2,130.00
			Total Amount	\$ 8,927.60

120 ✓

30

30

80

×

30

250

300

Acknowledged by Repairer

Signature:

Date: