

**BIKE PRODUCTION PTE LTD**  
610, Serangoon Road S(218216)  
Tel: 63922555, 62995177 Fax: 62975400  
**ROC/ GST Reg No.: 200007407G**

Date: 10 May 2020

**ASSESSMENT FOR REPAIR: YAMAHA CZD300A / XMAX300 - FBQ6089S**

Chassis No.:

Engine No.:

| <b><u>Qty</u></b> | <b><u>Description</u></b>                                                         | <b><u>Estimate</u></b> |
|-------------------|-----------------------------------------------------------------------------------|------------------------|
| 1 pc              | Front mudguard                                                                    | \$220.00               |
| 1 pc              | Right front fork                                                                  | \$580.00               |
| 1 pc              | Left front fork                                                                   | \$580.00               |
| 1 pc              | Front brake disk                                                                  | \$220.00               |
| 1 pc              | Steering stem                                                                     | \$255.00               |
| 2 pcs             | Steering stem bearings @ \$45.00                                                  | \$90.00                |
| 1 pc              | Right view mirror                                                                 | \$180.00               |
| 1 pc              | Left silver faring                                                                | \$350.00               |
| 1 pc              | Right silver faring                                                               | \$350.00               |
| 1 pc              | Right black fairing                                                               | \$290.00               |
| 1 pc              | Yamaha amblem                                                                     | \$50.00                |
| 1 pc              | Right footstep                                                                    | \$295.00               |
| 1 pc              | Handle bar                                                                        | \$280.00               |
| 1 pc              | Right balancer                                                                    | \$75.00                |
| 1 pc              | Right rear cover                                                                  | \$330.00               |
| 1 pc              | Right rear cover amblem                                                           | \$75.00                |
| 1 pc              | Right brake lever                                                                 | \$65.00                |
| 1 pc              | Right rear handle                                                                 | \$175.00               |
| 1 pc              | Exhaust assembly                                                                  | \$550.00               |
|                   |                                                                                   | <hr/>                  |
|                   |                                                                                   | \$1,895.00             |
|                   | Less discount 10%                                                                 | \$189.50               |
|                   |                                                                                   | <hr/>                  |
|                   |                                                                                   | \$1,705.50             |
|                   | <b><u>Special nett items</u></b>                                                  |                        |
| 1 pc              | Front sport rim                                                                   | \$550.00               |
| 1)                | Towing charges                                                                    | \$100.00               |
|                   | Replace, realign and adjust above damaged parts, check wiring and lighting system |                        |
| 2)                |                                                                                   | \$700.00               |
|                   | To replace and balance front wheel rim                                            |                        |
| 3)                |                                                                                   | \$150.00               |
|                   | To knock, straighten chassis & body balancing                                     |                        |
| 4)                |                                                                                   | \$380.00               |
| 5)                | Spray painting                                                                    | \$350.00               |
| 6)                | Reset meter                                                                       | \$120.00               |

|    |                                            |          |
|----|--------------------------------------------|----------|
| 7) | To replace and refit and align front forks | \$180.00 |
|----|--------------------------------------------|----------|

|                       |                   |
|-----------------------|-------------------|
| <b>Total Estimate</b> | <b>\$4,055.50</b> |
|-----------------------|-------------------|

**Note: The above estimate is subjected to the prevailing GST of 7%**

---

For Bike Production Pte Ltd