



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. AC2004206
INV Date 29/05/2020
Reference CS3/III20005668/Gvf3e2
Code III2



PROFESSIONAL SERVICE FEE

Vehicle No. FBF 1979P
Insured Veh. SHC 1513U
Claim No. MCT20050048
Policy No. MCOM0015
Accident Date 08/05/2020
Inspection Date 12/05/2020

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 12.05.2020 05.00pm	
- Dismantle Inspection 13.05.2020 04.52pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM