

Parts

No.	Particulars	%Disc	%Depr	Amount
	*Front windscreen <i>CRA</i>	0.00	0.00	*850.00 F
	*Front windscreen moulding <i>MC</i>	0.00	0.00	*190.00 F
	*Front panel "ISUZU" emblem <i>MC</i>	0.00	0.00	*155.00 F
	*Front grille assembly <i>Dis</i>	0.00	0.00	*350.00 F
	*RH head lamp <i>Dis</i>	0.00	0.00	*385.00 F
	*LH head lamp <i>Dis</i>	0.00	0.00	*385.00 F
	*RH signal lamp <i>Dis</i>	0.00	0.00	*195.00 F
	*LH signal lamp <i>Dis</i>	0.00	0.00	*195.00 F
	*Front bumper <i>BT</i>	0.00	0.00	*450.00 F
	*LH front bumper lamp <i>Dis</i>	0.00	0.00	*115.00 F
	*Front bumper bottom dust panel <i>CRA</i>	0.00	0.00	*140.00 F
	*RH front door window glass <i>Dis</i>	0.00	0.00	*240.00 F
	*RH front door window glass outer moulding <i>See</i>	0.00	0.00	*180.00 F
	*RH front door window glass inner moulding <i>See</i>	0.00	0.00	*165.00 F
	*RH front door front black garnish <i>See</i>	0.00	0.00	*220.00 F
	*RH front door bottom garnish <i>See</i>	0.00	0.00	*125.00 F
	*LH front door signal lamp <i>CRA</i>	0.00	0.00	*135.00 F
	*LH front door window glass <i>See</i>	0.00	0.00	*240.00 F
	*LH front door window glass outer moulding <i>See</i>	0.00	0.00	*180.00 F
	*LH front door window glass inner moulding <i>See</i>	0.00	0.00	*165.00 F
	*LH front door front black garnish <i>See</i>	0.00	0.00	*180.00 F
	*LH front door front black garnish <i>See</i>	0.00	0.00	*220.00 F
	*LH front door bottom garnish <i>See</i>	0.00	0.00	*125.00 F
	*RH front wheel cowling <i>See</i>	0.00	0.00	*160.00 F
	*RH front wheel cowling clips (1 set) <i>See</i>	0.00	0.00	*22.00 F
	*LH front wheel cowling <i>NN</i>	0.00	0.00	*160.00 F
	*LH front wheel cowling clips (1 set) <i>NN</i>	0.00	0.00	*22.00 F
	*LH rear wheel cowling <i>See</i>	0.00	0.00	*125.00 F
	*RH front wheel bearing <i>See</i>	0.00	0.00	*160.00 F
	*LH front wheel bearing <i>See</i>	0.00	0.00	*160.00 F
	*Front stabilizer bar <i>NN</i>	0.00	0.00	*240.00 F
	*RH front stabilizer bar <i>NN</i>	0.00	0.00	*140.00 F
	*LH front stabilizer bar <i>NN</i>	0.00	0.00	*140.00 F
	*RH front shock absorber <i>See</i>	0.00	0.00	*140.00 F
	*LH front shock absorber <i>See</i>	0.00	0.00	*140.00 F
	*RH steering tie rod <i>BT</i>	0.00	0.00	*180.00 F
	*LH steering tie rod <i>BT</i>	0.00	0.00	*180.00 F
	*RH steering tie rod end <i>BT</i>	0.00	0.00	*95.00 F
	*LH steering tie rod end <i>BT</i>	0.00	0.00	*95.00 F
	*Air con condensor <i>Dis</i>	0.00	0.00	*480.00 F
	*Air con condensor support bracket <i>BT</i>	0.00	0.00	*140.00 F
	*Air con condensor auto fan <i>CRA</i>	0.00	0.00	*450.00 F
	*RH rear wheel bearing <i>See</i>	0.00	0.00	*90.00 F
	*LH front sun visor <i>See</i>	0.00	0.00	*115.00 F
	*Engine air cleaner box <i>CRA</i>	0.00	0.00	*380.00 F

Sub Total (S\$)

9.399.00

+ Margin on L,N Items 15.00% (S\$)

1,409.85

Total Parts (S\$)

10,808.85

te Ltd/YP620E/11/05/2020 18:08. Not valid without Reference section.
Generated using **Merlmen e-Claims IEAS**