

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Priya

Date: 14 May 2020

Preliminary Advice

Vehicle No	: GBG6835H	Accident Date	: 13/05/2020
Make	: NISSAN NV200	Policy No.	: D19MFL0005549
Assignment Date	: 13/05/2020	Excess	: S\$0.00
Date of Inspection	: 13/05/2020	Est. Duration of Repair	: 4 days
Inspection At	: Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,833.10
Revised Amount	:S\$	2,181.60
Check Items (Estimated)	:S\$	181.50
Total	:S\$	2,363.10

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	31,571.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,429.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :