

ASS. REC. BY:

REF:

LPC/20005718/Kg

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 9799D

Yr Regn:

04, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault

Latitude c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

600938

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VFIABL 15AUC

277293

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sailun

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

12/5/20

D.O.I.

13/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2201

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9799D**AAD2005-027***Not Authorised*
44p \$220/h

Vehicle No.:

13 MAY 2020

Chassis No.:

SHD 9799D

Vehicle Make:

VF1ABL15AUC277293

Vehicle Model:

RENAULT

Date of Accident :

LATITUDE

Third Party Insurer :

12.5.2020

Date of Registration :

LONPAC

14/4/2014

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER REFLECTOR RH
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER REFLECTOR LH
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel) TRIM
- 1 TAILLAMP RH
- 1 TAILLAMP PANEL RH
- 1 TAILLAMP LH
- 1 TAILLAMP PANEL LH
- 1 BOOT REAR
- 1 BOOT FINISHER
- 1 BOOT WHEATERSTRIP
- 1 BOOT REFLECTOR LAMP LH
- 1 BOOT REFLECTOR LAMP RH
- 1 BOOT BADGE 'RENAULT'
- 1 BOOT BADGE
- 1 BOOT STRUT LH

LIST

\$	n (Pen)	561.70	X
\$	sn	411.90	}
\$	sn	98.10	
\$	sn	82.10	
\$	sn	59.80	
\$	sn	16.60	
\$	sn	80.80	
\$	sn	54.20	
\$	sn	16.60	
\$	n	547.80	
\$	n	114.50	
\$	n	100.90	
\$	n	745.80	
\$	sn	404.56	
\$	sn	313.10	
\$	n	401.40	
\$	sn	401.40	
\$	n	401.40	
\$	n	1,677.20	
\$	sn	344.70	
\$	sn	178.20	
\$	sn	277.70	
\$	sn	277.70	
\$	nn	82.40	
\$	nn	95.80	
\$	sn	145.10	

Trans-cab Auto Services Pte Ltd**AAD2005-027**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9799D

1	BOOT STRUT RH	\$	145.10	} <i>Sum X</i>
1	BOOT HINGE LH	\$	254.20	
1	BOOT HINGE RH	\$	253.80	
1	BOOT INNER TRIM BOARD	\$	611.00	
1	BOOT LOCK	\$	246.60	
1	EXHAUST CAP REAR	\$	125.40	
1	SPARE TYRE BOARD	\$	680.90	
TOTAL		\$	10,208.46	
10%		\$	1,020.85	
		\$	9,187.61	

Special Nett

1SET	PARKING AID	\$	<i>Sh</i> 700.00	} <i>X</i>
1SET	REAR BUMPER CLIP	\$	<i>nn</i> 68.00	
1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 35.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 25.00	
1SET	BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 35.00	
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 25.00	
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>nn</i> 35.00	
1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 30.00	
1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 68.00	
1	BOOT STICKER "Trans-cab"	\$	<i>nn</i> 35.00	
1	BOOT STICKER "6555-3333"	\$	<i>nn</i> 35.00	
1	BOOT INNER TRIM CLIP	\$	<i>nn</i> 45.00	
1SET	BOOT FINISHER CLIP	\$	<i>nn</i> 35.00	
1	TAILLAMP CLIP LH	\$	<i>nn</i> 25.00	
1	TAILLAMP CLIP RH	\$	<i>nn</i> 25.00	
1	Rear Bumper Protector	\$	<i>nn</i> 120.00	
1	REAR LICENCE PLATE WITH HOLDER	\$	<i>Sh</i> 100.00	
TOTAL		\$	1,441.00	

TOTAL PARTS \$ 10,628.61**LABOUR**

Trans-cab Auto Services Pte Ltd**AAD2005-027**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9799D

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	4 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4 6,000.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To reinstall rear bumper parking sensor.	\$	4 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	2'2 of
TOTAL	\$	14,170.00	

Over All Total \$ 24,798.61**LUMP SUM (REPAIR DAY)****20 DAYS**

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD9799D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 May 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C001050
Chassis No.:	VF1ABL15AUC277293
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Apr 2014
First Registration Date:	14 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Apr 2022
PARF Rebate Amount:	\$8,123.00
Intended COE Rebate Details	
COE Expiry Date:	13 Apr 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$59,871.00
COE Rebate Amount:	\$14,364.00
Total Rebate Amount:	\$22,487.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 May 2020

OK