



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG20000885/Fsf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 19-05-2020



ATTN : JEFFREY NG SAY KIAT

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMJ 5970K	Veh. Inspected	SKU 45E
Policy No.	1900045315	Coverage (\$)	0.00
Claim No.	2146182333SG	Excess (\$)	0.00
Assign From	JEFFREY NG SAY KIAT	Assign Date	14/05/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD1173422N214059	Colour	GREY
Odometer	107713	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	PIRELLI	7 mm
L/H Front Tyre	225/40 R18	PIRELLI	7 mm
R/H Rear Tyre	225/40 R18	PIRELLI	7 mm
L/H Rear Tyre	225/40 R18	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/01/2020	Inspection Date	14/01/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
--------------------------------------------	-----------------------