LKK Auto Consultants Pte Ltd (Co.Reg, No:199607198R) 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408833 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #09-16 Singapore 079120 To:

From:

LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Chan, Yoke Shi Date: 18 May 2020 Attn:

Preliminary Advice

: SMS8841H Accident Date : 13/05/2020 Vehicle No : AUDI A3 SPORTBACK Policy No. : 2070037067 Make Assignment Date : 15/05/2020 Excess : S\$300.00 Date of Inspection : 14/05/2020 Est. Duration of Repair : 14.00

: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699 Inspection At

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	86,611.00
Revised Amount	:S\$	59,634.00
Check Items (Estimated)	:S\$	16,974.00
Total	:S\$	76,608.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	134,250.00
Pre-Accident Value	:S\$	114,000.00
COE / PARF Rebate	:S\$	47,548.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	86,702.00
Margin for Repair (Pre-Accident Value)	:S\$	66.452.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments:

Pre-Accident Value