

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 19 May 2020

Preliminary Advice

Vehicle No	: SMS8841H	Accident Date	: 13/05/2020
Make	: AUDI A3 SPORTBACK	Policy No.	: 2070037067
Assignment Date	: 15/05/2020	Excess	: S\$300.00
Date of Inspection	: 14/05/2020	Est. Duration of Repair	: 14.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	87,143.00
Revised Amount	:S\$	59,365.00
Check Items (Estimated)	:S\$	16,974.00
Total	:S\$	76,339.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	134,250.00
Pre-Accident Value	:S\$	114,000.00
COE / PARF Rebate	:S\$	47,548.00
Salvage Value	:S\$	
Margin for Repair (New for old Value)	:S\$	86,702.00
Margin for Repair (Pre-Accident Value)	:S\$	66,452.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :