

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 24 Jun 2020

Preliminary Advice

Insured Vehicle No	: GBF8832H	Accident Date	: 15/05/2020
TP Vehicle No	: SKP1129S	Assignment Date	: 18/05/2020
Make	: TOYOTA ALPHARD	Est. Duration of Repair	: 6.00
Date of Inspection	: 20/05/2020		
Inspection At	: LIM YEW BOO SPRAY PAINT CO (HQ) BLK 10 SIN MING INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,494.56
Revised Amount	:S\$	8,801.46
Check Items (Estimated)	:S\$	
Total	:S\$	8,801.46

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.