

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 26 May 2020

SUPPLEMENTARY REPAIR: YAMAHA GDR155A (AEROX) - FBQ8256M

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Left inner black cover	\$85.00 ✓ DFF
1 pc	Right inner black cover	\$85.00 ✓ DFF
1 pc	Headlamp assy	\$295.00 ✓ CAC
1 pc	Upper inner cover centre	\$145.00 ✓ SCR.
		<hr/>
		\$610.00
	Less discount 10%	\$61.00
		<hr/>
		\$549.00
	<u>Special nett items</u>	
		<hr/>
	Total Estimate	<hr/>
		\$549.00

Note: The above estimate is subjected to the prevailing GST of 7%

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



For Bike Production Pte Ltd