

Surveyor

PKS
Cal.

REF:

CTi

ASSIGNMENT

(-2021)

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Speedy Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$10k

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBF 1986T

Yr Regn: 14 Mon 2011

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha

YZF-R1 c.c. 998

Colour: Black

A/C: Insured / Std / NI / NA

Sp.Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JYARN 221 000010383

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70ZR17

R: 190/50ZR17

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. 4 mm

L/Bal. 4 mm

D.O.A. _____

D.O.I. 23-08-19

Survey held at w/s

6pm

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated cost: 448
Repair range \$7000 - \$8000

126/8/2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1) 20/05 Typist

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee: 190

Transportation: _____

S + RS. _____

Photos

Others

TOTAL

190

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp * (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format : MER-TP

Lump Sum 7100