

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 May 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA7871G/19/05/2020 16:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET ASSY <i>x(R)</i>	20.00	0.00	*2,265.90 FL
2	1		*HEAD LAMP LH <i>scr</i>	20.00	0.00	*1,388.00 FL
3	1		*FRONT BUMPER ASSYH <i>crs/100</i>	20.00	0.00	*1,052.20 FL
4	1		*FRONT BUMPER SIDE LH <i>xnn</i>	20.00	0.00	*14.30 FL
5	1		*FRONT BUMPER TOP BRACKET LH <i>xnn</i>	20.00	0.00	*22.40 FL
6	1		*FRONT SUPPORT PANEL <i>xnn</i>	20.00	0.00	*907.40 FL
7	1		*FRONT ADVERTISEMENT <i>nee</i>	20.00	0.00	*100.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)

5,750.20

- List Item Discount on L Items (\$\$)

1,150.04

Total Parts (\$\$)

4,600.16

ComfortDelGro Engineering Pte Ltd/SHA7871G/19/05/2020 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

$$\begin{aligned}
 & \$1388 \\
 & + \$1052.20 \\
 & \hline
 & \$2440.2 \\
 & \times 75\% \\
 & \hline
 & = \$1830.15 + \$100 \\
 & \hline
 & = \$1930.15
 \end{aligned}$$
Net Item

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING <i>fender / Bonnet</i>	New	<i>\$700</i> 720.00
2	SPRAY PAINTING	New	<i>\$400</i> 500.00
3	CHECH WIRING	New	<i>\$30</i> 50.00
4	REMOVR/REFIX AC CONDENSER & CHARGE GAS	New	<i>xnn</i> 120.00
5	TUFF KOTE	New	<i>xnn</i> 60.00
Gross Labour Cost (\$\$)			1,450.00

ComfortDelGro Engineering Pte Ltd/SHA7871G/19/05/2020 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour: \$1130/=

Rqm (Ltr)

20/05/2020 1410

Parasuram@lkkauto.com

88622728

(L/S)

alt repair plate

(3) repair days

Part: \$1930.15

Labour: \$1130/=

Total: \$3060.15

L/S: \$2450/=