



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20005847/Eyf3e2

50 RAFFLES PLACE
#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 02-06-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 7980Z	Veh. Inspected	SJV 4084Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD20001635/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	20/05/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	ZGE200026835	Colour	SILVER
Odometer	194748	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	HABILEAD	5 mm
L/H Front Tyre	195/65 R15	HABILEAD	5 mm
R/H Rear Tyre	195/65 R15	HABILEAD	5 mm
L/H Rear Tyre	195/65 R15	HABILEAD	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/05/2020	Inspection Date	26/05/2020
Survey held at	EXCLUSIVE ENTERPRISE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**