LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

То : AIG Asia Pacific Insurance Pte. Ltd.

Attn : MdNoor, Norsiah

Your Ref : 5441981264SG

Our Ref : CC6/AIG20005913/UKA3

Date : 03 Dec 2020 "WITHOUT PREJUDICE"

ACCIDENT INVOLVING SJJ4515J & FBG8259H ON 02/05/2020

Refer to the above accident.

It is a head-to-rear collision. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have successfully / not successfully carried out TP Express Settlement between your insured (vehicle no. SJJ4515J) and third party claimant (vehicle no. FBG8259H).

Summary of offer made to workshop Ban Hock Hin Co. Pte Ltd is as follows:

	Claimed	Revised
1) Cost of Repairs(w/GST)	\$ 4,342.49	\$ 1,498.00 (subect to repair invoice)
2) Loss of Use	\$ TBA	\$ 180.00 (6days x \$30.00)
3) LTA/GIA Search Fee	\$ TBA	\$ 7.45 (subject to receipt)

Amount of claim at Liability 100% 1,685.45

For your approval please.

Regards,

CHEW HSIAO TONG

LKK Auto Consultants Pte Ltd

^{*}Recommended 5 repair days + 1Sunday = 6days