



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLV3207T
Date of Accident : 18 September 2019

Mr Leong Meng Fai (Liang Minghui)

Date : 22 May 2020

Estimate To Repair FBN4928A - Piaggio Vespa Sprint Sport 150 E4
Chassis No : ZAPMA140000001967

166 - Marous
26/5/2020 09/10h

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	o/s head fairing chrome moulding	\$ 75.00
02	2 ps	side mirror assy @ \$160.00	\$ 320.00
03	1 pc	rear exhaust chrome protector cover	\$ 85.00
04	1 pc	o/s side fairing chrome moulding	\$ 65.00
			\$ 545.00
Less 10 %			\$ 54.50
			\$ 490.50
<u>SPECIAL NETT ITEMS</u>			
05	1 pc	rear licence plate	\$ 50.00
			\$ 50.00
<u>LABOUR & MISC. CHARGES</u>			
01		Towing charges.	\$ 80.00
02		To check electrical lighting concerned.	\$ 50.00
03		Labour to dismantle fairing for facilitate repair.	\$ 350.00
04		Labour charges.	\$ 850.00
05		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 2,530.00
Total			\$ 3,070.50

not Authorized

26/5/20

to keep after rep.

6 days

rear box cut

Supply

Box

number plate

visor

front visor scd

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: