

ASS. REC. BY:

REF:

PC2/20005918/Kea3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$21K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JTC 25946 Yr Regn: 02, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPV

Make: Toy wish c.c. 1794

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 17.2188 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 7NE10 0382879

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/5/20 D.O.I. 26/5/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/6 11:30 @ 34501. Confirm

Date/Time, File Pass to?

☐: Prell. Report

1)

☐: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐: Site Insp (\$ _____)☐: Interview (\$ _____)☐: Tech Invs (\$ _____)☐: Weekend (\$ _____)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJC2594E
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

ATTN: Motor Claim Department

FAX: 65073849

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 21/05/2020

TP Veh Reg No: SHC3566D

Not Withheld

1/1 Sup &

Runny After Paint

5 days

Estimate No: ES2090418/YISHUN

Date: 22 May 2020

Policy No: DMPPHQ20-000451

Veh Reg No: SJC2594E

Make/Model: TOYOTA TOYOTA

WISH 1.8X A

Chassis No: ZNE100382879

Engine No: 1ZZ2974785

Reg. Date: 04/02/2008

Estimate Repair Cost to Vehicle No :SJC2594E

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	530.50	1 PC	530.50	✓
2 REAR BUMPER LH BRACKET	48.44	1 PC	48.44	✓
3 REAR BUMPER LH SIDE RETAINER	57.70	1 PC	57.70	✓
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 REAR TAILGATE	1,210.40	1 PC	1,210.40	✓
6 TAILGATE LOGO	50.20	1 PC	50.20	✓
7 TAILGATE OUTER MOULDING	239.10	1 PC	239.10	✓
8 TAILGATE INNER LOCK	443.50	1 PC	443.50	✓
9 TAILGATE INNER RUBBER	304.10	1 PC	304.10	✓
10 REAR WINDSCREEN GLASS MOULDING	97.20	1 PC	97.20	✓
11 REAR END PANEL OUTER	590.60	1 PC	590.60	✓
12 REAR END PANEL TOP INNER GARNISH	232.90	1 PC	232.90	✓
			3,825.64	
		Less 25%	956.41	2,869.23
Special Net				
13 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
14 REVERSE SENSOR	200.00	1 SET	200.00	✓
			240.00	240.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
16 REMOVE & REFIX REAR BUMPER	750.00	1 LA	750.00	✓
ASY, TAILLAMPS, TAILGATE & ATTACHMENT, CUT, WELD & RENEW REAR PANEL OUTER, KNOCK & REPAIR REAR INNER PANEL & REALIGN THE SAME	750.00	1 LA	750.00	✓
17 PUTTY & RESPRAY ON REAR BUMPER, REAR END PANEL, TAILGATE & REAR AFFECTED AREAS	50.00	1 LA	50.00	✓
18 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00	✓
19 RUSTPROOFING			1,710.00	1,710.00

Total S\$ 4,819.23

Add GST @ 7% 337.35

Total Amount Payable S\$ 5,156.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

SJC2594E

7/2/7C

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 295B

Vehicle Details

Vehicle No.: SJC2594E
Vehicle to be Exported: No
Intended Deregistration Date: 22 May 2020
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8X A
Primary Colour: Black
Manufacturing Year: 2007
Engine No.: 1ZZ2974785
Chassis No.: ZNE100382879
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$17,976.00
Original Registration Date: 04 Feb 2008
First Registration Date: 04 Feb 2008
Transfer Count: 2
Actual ARF Paid: \$19,774.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 03 Feb 2023
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$25,289.00
COE Rebate Amount: \$13,654.00
Total Rebate Amount: \$13,654.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 May 2020

OK