

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJC2594E

TP/FC

M/S: MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES2090418/YISHUN

Date: 22 May 2020

Policy No: DMPPHQ20-000451

Veh Reg No: SJC2594E

Make/Model: TOYOTA TOYOTA

WISH 1.8X A

Chassis No: ZNE100382879

Engine No: 1ZZ2974785

Reg. Date: 04/02/2008

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 21/05/2020

TP Veh Reg No: SHC3566D

Not Notified

11 Day &

Money After Paint

5 days

Estimate Repair Cost to Vehicle No :SJC2594E

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	530.50	1 PC	530.50	✓
2 REAR BUMPER LH BRACKET	48.44	1 PC	48.44	✓
3 REAR BUMPER LH SIDE RETAINER	57.70	1 PC	57.70	✓
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 REAR TAILGATE	1,210.40	1 PC	1,210.40	✓
6 TAILGATE LOGO	50.20	1 PC	50.20	✓
7 TAILGATE OUTER MOULDING	239.10	1 PC	239.10	X
8 TAILGATE INNER LOCK	443.50	1 PC	443.50	✓
9 TAILGATE INNER RUBBER	304.10	1 PC	304.10	✓
10 REAR WINDSCREEN GLASS MOULDING	97.20	1 PC	97.20	✓
11 REAR END PANEL OUTER	590.60	1 PC	590.60	✓
12 REAR END PANEL TOP INNER GARNISH	232.90	1 PC	232.90	✓
			3,825.64	
		Less 25%	956.41	2,869.23
Special Net				
13 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
14 REVERSE SENSOR	200.00	1 SET	200.00	✓
			240.00	240.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
16 REMOVE & REFIX REAR BUMPER	750.00	1 LA	750.00	✓
ASY, TAILLAMPS, TAILGATE & ATTACHMENT, CUT, WELD & RENEW REAR PANEL OUTER, KNOCK & REPAIR REAR INNER PANEL & REALIGN THE SAME				
17 PUTTY & RESPRAY ON REAR BUMPER, REAR END PANEL, TAILGATE & REAR AFFECTED AREAS	750.00	1 LA	750.00	650.00
18 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
19 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,710.00	1,710.00

Total S\$ 4,819.23

Add GST @ 7% 337.35

Total Amount Payable S\$ 5,156.58

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: