Labour Works/ Panel Beating Related Works		2
Job Scope		Quotation
O RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN, STRAIGHTENED MEMBER	S	1,400.00
O REMEW DAMAGED LAKES, RELEACE, SERVI, WESS VALVE		1000
Spray Painting		Quotation
Job Scope	S	1,400.00
TO RESPRAY AFFECTED AREAS	1	-
		(00)
Others Cost (Accident Repair Related Expenses)		
	6	Quotation
Others Cost (Accident Repair Related Expenses) Job Scope	\$	Quotation
Others Cost (Accident Repair Related Expenses) Job Scope TO TUFFCOAT AFFECTED AREA TO REMOVE (REFIT FRONT CONDENSER AND TOP UP GAS FOR SUPPORT PANEL REPLACE	\$	Quotation 150.00
Others Cost (Accident Repair Related Expenses) Job Scope TO TUFFCOAT AFFECTED AREA TO REMOVE / REFIT FRONT CONDENSER AND TOP UP GAS FOR SUPPORT PANEL REPLACE LABOUR TO REMOVE / REFIT / REPLACE FRONT UNDERCARRIAGE	\$	Quotation 150.0 2 120.0 2 200.0
Others Cost (Accident Repair Related Expenses) Job Scope TO TUFFCOAT AFFECTED AREA TO REMOVE / REFIT FRONT CONDENSER AND TOP UP GAS FOR SUPPORT PANEL REPLACE LABOUR TO REMOVE / REFIT / REPLACE FRONT UNDERCARRIAGE TO PERFORM COMPUTERISED WHEEL ALIGNMENT BEFORE / AFTER	\$ \$ \$	Quotation 150.0 2 120.0 200.0 160.0
Others Cost (Accident Repair Related Expenses) Job Scope TO TUFFCOAT AFFECTED AREA TO REMOVE / REFIT FRONT CONDENSER AND TOP UP GAS FOR SUPPORT PANEL REPLACE LABOUR TO REMOVE / REFIT / REPLACE FRONT UNDERCARRIAGE TO PERFORM COMPUTERISED WHEEL ALIGNMENT BEFORE / AFTER	\$	Quotation 150.0 2 120.0 2 200.0 3 160.0
Others Cost (Accident Repair Related Expenses) Job Scope TO TUFFCOAT AFFECTED AREA TO REMOVE / REFIT FRONT CONDENSER AND TOP UP GAS FOR SUPPORT PANEL REPLACE LABOUR TO REMOVE / REFIT / REPLACE FRONT UNDERCARRIAGE TO PERFORM COMPUTERISED WHEEL ALIGNMENT BEFORE / AFTER TO PERFORM COMPUTERISED FAULT CODE CLEARANCE AND SETTLING	\$ \$ \$	Quotation 159.0 120.0 200.0 160.0 × 160.0 30150.0
Others Cost (Accident Repair Related Expenses) Job Scope TO TUFFCOAT AFFECTED AREA TO REMOVE / REFIT FRONT CONDENSER AND TOP UP GAS FOR SUPPORT PANEL REPLACE LABOUR TO REMOVE / REFIT / REPLACE FRONT UNDERCARRIAGE TO PERFORM COMPUTERISED WHEEL ALIGNMENT BEFORE / AFTER	\$ \$ \$	Quotation 159.0 2 120.0 200.0

CAS GARAGE PTE LTD

UEN 201828067M 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171 Email: allangoh.cas@gmail.com

Fax: 6509 9501

2410.

total: 11.212.

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey beforefalter spray painting:

• To display damaged part(s) during resurvey:

• Parts prices are subject to confirmation:

• Third party survey is on a "Vilinout Prejudic"

• No illegal modification(s) is allowed:

• No illegal modification(s) as allowed:

• Supplementary item(s) must be resurveyed: