



ESTIMATE BILL(SUPPLEMENTARY)

Date : 6 August 2020
 To :
 Owner : Neighbour Roy Grenville
 Vehicle Reg. No. : SGR171L
 Make/Model : Porsche C4SCoupe Tip
 Chasis No. : WP0ZZZ99Z8S723763
 Year Mfg : 2008
 Date of Accident : 22-May-20

ESTIMATE COST OF REPAIR TO "PORSCHE C4SCOUPE TIP"			
" REG. NO. SGR171L"			
QUANTITY	DESCRIPTION	UNIT PRICE	AMOUNT
	<u>Special Nett Items:</u>		
1	RHR Cross Member		2,247.00
1	RHR Axle Side Panel		749.00
1	Rear Anti-Roll Bar		1,498.00
1	Rear Absorber Sponge		59.90
1	Rear Absorber Top Mounting		449.40
	Total Special Nett Items		5,003.30
	<u>Labour Charges:</u>		
	To check wheel alignment after repairs 17.07.2020, 03.08.2020, 07.08.2020		200.00
	To jack up to check, re-fix chassis alignment		800.00
	To symetrical specifications on cross member		267.50
	To hoist up to check, refix under carriage : 28 May, 13 July, 3 Aug		2,400.00
	Total Labour		3,667.50
	ESTIMATE PARTS AND LABOUR GRAND TOTAL \$		8,670.80

* Pls note that wheel alignment was done on 28.05.2020 after the accident to determine readings & potential parts to be replaced