

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFG8188G/2005053

26th May 2020

The Manager

Motor Claim Dept.

AIG Asia Pacific Insurance Pte Ltd

CHARTIS Building

78 Shenton Way #07-16

Singapore 079120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of Accident

: 06th May 2020

Location

: Whitley Road toward Steven Rd

Third Party Claim Vehicle No

: SMM 560 C

Repair Cost For Vehicle No

: SFG 8188 G (BMW 428i)

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front door assy. LH <i>300500</i>	1	1650.00	\$ 1,650.00 ✓
2	Front door regulator gear LH <i>17</i>	1	340.00	\$ 340.00 x
3	Front door power window motor LH <i>11</i>	1	350.00	\$ 350.00 x
4	Front door weather strip LH <i>11</i>	1	200.00	\$ 200.00 x
5	Front outer frame moulding LH <i>all</i>	1	128.10	\$ 128.10 ✓
				\$ 2,668.10
6	Front sound proof shield LH (s/nett) <i>all</i>	1	180.00	\$ 180.00 <i>150 s.n</i>
				\$ 2,848.10

Labour Charges :-

Cut out, renew, knocking & welding, front door assy. LH, remove & install all damage parts, straighten & re-align body

Tuff-kote on damage parts

Remove & install front door lock, power window gear & regulator etc

Reset & diagnosis

Spray painting on damage parts

Check lighting after repair

Labour charge

Total amount

GST will be reflected in the final bills.

Amounts

\$ 780.00 *300*

\$ 40.00 *30*

\$ 250.00

\$ 300.00 *80*

\$ 900.00 *500*

\$ 65.00 *20*

\$ 2,335.00

\$ 5,183.10

Notes :-

Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

2-1778.1
52
1689.19
2769.19
2215

not Acknowledged
the other repair
3 days
28/5/20
1/5 2200