

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 18 Nov 2020

Preliminary Advice

Insured Vehicle No : YL851B
TP Vehicle No : SKX4721U
Make : HONDA ACCORD
Date of Inspection : 28/05/2020
Inspection At : ADVANCE AUTO GARAGE
10 KAKI BUKIT ROAD 2, #01-21 FIRST EAST CENTRE
SINGAPORE 417868
Accident Date : 25/01/2020
Assignment Date : 02/06/2020
Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,136.60
Revised Amount	:S\$	3,150.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,150.20

Lump Sum Repair	:S\$	2,500.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :