

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz Reg No: 199101494Z
GST No: M200985052



Volkswagen SKODA

Commercial Vehicles

Quotation

Non binding - Preview

Page

1/3

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Seletar Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
TAN
KIM CHENG JUNE
142 SERANGOON NORTH AVENUE 1
#04-325
Singapore 550142

Document no
Document date 02-06-2020
Customer no 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2020009113/ 1
Job order date 28-05-2020
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLK7556S	BQ13HZC0	31-01-2020	WVWZZZAUZKW196593	Golf Comfortline 1.4 TSI 92kW DSG	15

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00 ✓	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00 ✓	#1	480.00	513.60
D 169300M2	1k Window Adhesive	2	pcs.	49.51 ✓ nec	#1	99.02	105.95
D 002000A2	Adhesive Remover	1	pcs.	114.78 ✓ nec	#1	114.78	122.81
D 00920002	Primer	1	pcs.	25.74 ✓ nec	#1	25.74	27.54
D 181802M1	Activator For Precoated W	1	pcs.	23.77 ✓ nec	#1	23.77	25.43
D 00950025	Applicator	2	pcs.	9.39 ✓ nec	#1	18.78	20.09
5G6827025AA	Heckklappe	1	pcs.	1,952.18 ✓	#1	1,952.18	2,088.83
	REAR BOOT LID						
5G6827505B 9B9	Hood Latch Satin Black	1	pcs.	352.43 ✓	#1	352.43	377.10
	BOOT LID LOCK						
5G0827469Q FOD	Betätigung Mit Mikroschal	1	pcs.	1,643.63 ✓	#1	1,643.63	1,758.68
	LID OPER MECHANISM						
5G6827705E	Gasket	1	pcs.	254.30 ✓	#1	254.30	272.10
	BOOT WETHERSTRIP						
5G0945087B	Additional Brake Light Wi	1	pcs.	158.79 ✓	#1	158.79	169.91
	3RD BRAKE LIGHT						
5G0853687 2ZZ	Inscription Bright Chrome	1	pcs.	75.22 ✓	#1	75.22	80.49
	NAME PLATE (GOLF)						
5G0945093AH	Led Tail Light	1	pcs.	534.20 ?	#1	534.20	571.59
	TAILLIGHT INNER LH						
5G0945094AH	Led Tail Light With Rear	1	pcs.	534.20 ?	#1	534.20	571.59
	TAILLIGHT INNER RH						
5G6867605E 82V	Trim Panel For Hatch Gate	1	pcs.	153.49 ?	#1	153.49	164.23
	BOOT LID TRIM COVER						
5G6807417BQGRU	Cover For Bumper Primed	1	pcs.	1,124.14 ✓	#1	1,124.14	1,202.83
	REAR BUMPER						
5G6807568R 9B9	Rear Diffusor Satin Black	1	pcs.	312.15 ✓	#1	312.15	334.00
	BUMPER SPOILER						
WHT005263	POP-RIVET	4	pcs.	1.09 ✓	#1	4.36	4.67
5G0807305D	Bumper	1	pcs.	604.40 ✓	#1	604.40	646.71
	BUMPER REINFORCEMENT						
5G6807863C	Attachment Strip	1	pcs.	63.22 ✓	#1	63.22	67.65
	BUMPER CENTRE BRACKET						
5G6807393A	Guide Piece	1	pcs.	36.38 ✓	#1	36.38	38.93
	TAILLIGHT LOWER BRACKET LH						
5G6807394A	Guide Piece	1	pcs.	36.38 ✓	#1	36.38	38.93
	TAILLIGHT LOWER BRACKET RH						
5G6807393	Guide Piece	1	pcs.	36.38 ✓	#1	36.38	38.93
	BUMPER SIDE BRACKET LH						
5G6807394	Guide Piece	1	pcs.	36.38 ✓	#1	36.38	38.93
	BUMPER SIDE BRACKET RH						
5G0919491D	Sensor Bracket	2	pcs.	11.90 ✓	#1	23.80	25.47
5G0919491E	Sensor Bracket	1	pcs.	11.90 ✓	#1	11.90	12.73
5G0919492D	Sensor Bracket	1	pcs.	12.60 ✓	#1	12.60	13.48
5Q0919275B GRU	Sensor Primed	2	pcs.	168.10 ✓	#1	336.20	359.73
5Q0919133 9B9	Seal Ring Satin Black	2	pcs.	1.18 ✓	#1	2.36	2.53

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz Reg No 199101494Z
GST No M200985052



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page

2/3

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Serangoon Way
#07-16 A/C Building
Singapore 079120

Customer Details:
Ms.
TAN
KIM CHENG JUNE
142 SERANGOON NORTH AVENUE 1
#04-325
Singapore 550142

Document no.
Document date 02-06-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2020009113/ 1
Job order date 28-05-2020
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLK7556S	BQ13HZC0	31-01-2020	WVWZZZAUZKW196593	Golf Comfortline 1.4 TSI 92kW DSG	15

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5G0971104AD	Harness For Bumper	1	pcs.	89.04	X nn #1	89.04	95.27
	SENSOR WIRE HARNESS						
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	75.94	rec #1	75.94	81.26
D 822150A1	Bonding Agent For Plastic	1	pcs.	59.40	rec #1	59.40	63.56
1K8943021	License Plate Light	2	pcs.	38.01	m.s #1	76.02	81.34
5G6853333 ZZ	Decorative Moulding Brigh	1	pcs.	141.09	? X #1	141.09	150.97
	BUMPER LOWER CHROM (CENTRE)						
5G6853331A ZZ	Decorative Moulding Brigh	1	pcs.	116.01	? X nn #1	116.01	124.13
	BUMPER LOWER CHROM (LH)						
5G6853332A ZZ	Decorative Moulding Brigh	1	pcs.	116.01	? nn #1	116.01	124.13
	BUMPER LOWER CHROM (RH)						
5G6813301E	Abschlussblech Hinten	1	pcs.	674.84	? #1	674.84	722.08
	END PANEL INNER						
5G6813309	End Plate	1	pcs.	118.44	? de #1	118.44	126.73
	END PANEL OUTER						
N 90652602	Weld Stud	8	pcs.	0.61	? rec #1	4.88	5.22
	BOLT						
D 007500A2	Zinc Spray	1	pcs.	62.88	? rec #1	62.88	67.28
D 180003M2	2k-Body Adhesive	1	pcs.	406.76	? rec #1	406.76	435.23
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	61.67	? rec #1	61.67	65.99
5G6863459K 82V	Cover For Lock Carrier Ti	1	pcs.	164.17	? de #1	164.17	175.66
	END PANEL TRIM COVER						
5G6858855J CA9	Cargo Platform Black	1	pcs.	415.75	? de #1	415.75	444.85
	SPARE WHEEL COVER						
1K0803899D	Bolt For Spare Wheel Moun	1	pcs.	15.86	? nn #1	15.86	16.97
	SPARE WHEEL BOLT						
	LABOUR	84	pcs.	840.00	#1 3360	6,720.00	7,190.40
	SPRAY PAINT	23	pcs.	800.00	#1 2400	5,600.00	5,992.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRASFER BOOT LID MECHANISM	1	pcs.	840.00	#1 420	840.00	898.80
	R&R REAR LUGGAGE TRIM	1	pcs.	840.00	#1 420	840.00	898.80
	REAR NAMBER PLATE	1	pcs.	80.00	#1 67	80.00	85.60
	AXA VS AIG AGAINST VEHICLE SLL7341P						
	D O A 28-05-2020						

Quotation valid till 04-06-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	26,099.94	7%	1,880.20	26,859.94	28,740.14
Total	760.00	26,099.94		1,880.20	26,859.94	28,740.14

End panel, Bood lid, Bumper

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 3/3

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
TAN
KIM CHENG JUNE
142 SERANGOON NORTH AVENUE 1
#04-325
Singapore 550142

Document no.
Document date 02-06-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2020009113/ 1
Job order date 28-05-2020
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLK7556S	BQ13HZC0	31-01-2020	WWWZZZAUZKW196593	Golf Comfortline 1.4 TSI 92kW DSG	15

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

Tan Jie 97495749
WP
2/6/20 @ 1030
Resurvey before paint.
tanjiah @ lkkauto.com.
09 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary or Omitted List



VEHICLE NUMBER: **SLK7556S**

MODEL **GOLF**

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
	CHECK WATER LEAKAGE	1	\$ 150.00	\$ 150.00 rec
Total				\$150.00

<u>No.</u>	<u>Item No.</u>	<u>Description</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Discount</u>	<u>Amount</u>	
1	8K0973702	LICENSE PLATE LIGHT WIRE HOUSING	1	\$ 10.35		\$ 10.35	cut
2	5G6858831 82V	SPARE WHEEL COVER BRACKET LH	1	\$ 50.76		\$ 50.76	de
3	5G6858832 82V	SPARE WHEEL COVER BRACKET RH	1	\$ 50.76		\$ 50.76	de
TOTAL:						\$111.87	

Total Labour & Parts

\$261.87

Survey By