

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 May 2020

Preliminary Advice

Vehicle No	: SGW2345M	Accident Date	: 27/05/2020
Make	: BMW 116I	Policy No.	: DMPG20006011
Assignment Date	: 29/05/2020	Excess	: S\$0.00
Date of Inspection	: 29/05/2020	Est. Duration of Repair	: 4 days
Inspection At	: Advance Auto Garage 10 Kaki Bukit Road 2, #01-21 First East Centre Singapore 417868		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,917.75
Revised Amount	:S\$	7,998.85
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,998.85

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	41,610.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,390.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :