

(FINALIZATION REPORT)

ETHOZ

Date : 15/06/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000053 Accident Date : 22/05/2020

Vehicle No : SML-4816-U Make & Model : HONDA VEZEL 1.5 (A) X

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	TAILGATE SENSOR <i>SUPPLEMENTARY ITEM</i>	455.20	285.40 <i>cr</i> ✓ 455.20
1	TAILGATE	1475.20	1100.90 ✓ 1475.20
1	TAILGATE WINDSCREEN SEAL	74.60	74.60
1	TAILGATE EMBLEM CENTRE	71.10	71.10
1	TAILGATE EMBLEM "VEZEL"	65.50	65.50
1	TAILGATE LOCK	342.20	<i>nn</i> X 0.00
1	TAILGATE RUBBER	224.30	<i>nn</i> X 0.00
1	REAR BUMPER	674.50	674.50
10	REAR BUMPER CLIP	45.00	45.00
1	REAR BUMPER SIDE BRACKET LH	65.50	<i>nn</i> X 0.00
1	REAR BUMPER SIDE BRACKET RH	65.50	<i>nn</i> X 0.00
1	REAR BUMPER REFLECTOR LH	95.20	95.20
1	REAR END PANEL <i>CHECK ITEM</i>	741.30	530.90 <i>bf</i> ✓ 741.30
1	TOOL KIT COVER (SPONGE)	285.40	285.40

PAGE : 1

Date : 15/06/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000053 Accident Date : 22/05/2020

Vehicle No : SML-4816-U Make & Model : HONDA VEZEL 1.5 (A) X

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	SPARE TYRE PANEL RESTORE	0.00	0.00
	Sub Total	4680.50	3983.00
	Discount 20% On Parts	(936.10)	(796.60)
		(0.00)	2582.80
Special Nett Item			
1	WINDSCREEN SEALANT	60.00	60.00
1	END PANEL SEALANT <i>CHECK ITEM</i>	40.00	40.00
1	REVERSE SENSOR	220.00	200.00
	Sub Total	320.00	300.00
Labour & Misc			
	LABOUR TO CARRY OUT REAR REPAIR	700.00	600.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	35.00
	TO SPRAY PAINTING ON REAR AFFECTED	600.00	500.00



Date : 15/06/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000053 Accident Date : 22/05/2020

Vehicle No : SML-4816-U Make & Model : HONDA VEZEL 1.5 (A) X

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	AREA		
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	30.00
	TO DETACH & RENEW REVERSE SENSOR	60.00	30.00
	TO TRANSFER TAILGATE FITTING	100.00	60.00
	TO REMOVE & INSTALL REAR TAILGATE GLASS	150.00	120.00
	TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS, GARNISH, CARPET, FLOOR MATS & SEAT	100.00	60.00
	Sub Total	1785.00	1435.00

Date : 15/06/2020
 To : INDIA INTERNATIONAL INSURANCE PTE LTD
 Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
 Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D19MTRENT000053 Accident Date : 22/05/2020
 Vehicle No : SML-4816-U Make & Model : HONDA VEZEL 1.5 (A) X

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
-----	-------------	-------------------	-------------------

Sub Total	5,849.40	4,921.40
GST 7.0 %	409.46	344.50
Total	6,258.86	5,265.90

COR : \$ 3,900.00 (4/5 REPAIR)

5 REPAIR DAYS

Surveyor Name : TAUFIK - LKK

Date & Time : 29/05/2020 3:30:00 PM

Lee Chen Sin

CLAIM DEPARTMENT

DID : 66547520

FAX :

PARTS - \$ 3,983.00 - 20%
 - \$ 3,186.40
 SN - \$ 300.00
 LABOUR - \$ 1,435.00
 \$ 4,921.40
 - 20% (4/5 REPAIR)
 \$ 3,937.12

2582.80
 300
 1435
 4317.80
 4/5 \$3450
 5 days #

PAGE : 4

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 15/06/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

SUPPLEMENTARY

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000053

Accident Date : 22/05/2020

Vehicle No : SML-4816-U

Make & Model : HONDA VEZEL 1.5 (A) X

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	TAILGATE SENSOR	285.40 455.20	Cra ✓
	Sub Total	455.20	
	Discount 20% On Parts	(91.04)	

Remarks:

364.16

SUB TOTAL

GST 7.0 % 25.49

TOTAL 389.65

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____

PAGE :