

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: auburnauto.claim@gmail.com

Vehicle No: SML521X

Model: Hyundai Avante

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Front bumper side grille (LH) / CUT \$	180.00 92-60 /
2 /	Front bonnet L/H & R/H fog lamp cover (LH) / CUT \$	440.00 115-40 /
1	Front bonnet lock Bumper lower spoiler / CUT \$	380.00 265-20 /
1	Front bonnet inner rubber X N/A \$	68.20 X
1	Front bonnet outer rubber X N/A \$	86.20 X
1	Front bumper inner sponge X N/A \$	135.90 X
1 2	Front bumper side retainers / DR \$	145.20 /
1	Front fender inner shield (LH) / CRV \$	426.50 265 /
1	Front headlamp lower bracket / DR (LH) \$	186.00 98-20 /
1	Front grille chrome moulding Bumper fog lamp LH / CUT \$	285.90 165-80 /
1	Front grille logo / NR \$	188.80 71 /
1	Front grille / DR \$	628.60 /
1	Front Bumper / DR \$	1,250.00 785-80 /
1	Front bonnet lock X N/A \$	380.00 X
2	L/H and R/H Mud Flap X N/A \$	160.00 X
2 /	L/H Headlight (LH) / DR (HID type) \$	1,500.00 /
1	Bonnet Front LH Rim / CUT \$	950.00 600 /
1	Front L/H Fender / DR \$	660.00 /
1	Car Plate and Carplate Holder X N/A \$	190.00 X
1	Chrome "Hyundai" logo X N/A \$	135.00 X

5392.80
- 20%
4314.24

\$ 8,376.30

c/f: \$ \$ 8,376.30

	Special Nett Items	AMT S\$
1	Rear Windscreen Sealant X MM	\$ 120.00
1	Front bumper clip / n	\$ 150.00 J
		<u>\$ 270.00</u>

30

S/N.

Labour Charges

Remove and refit Front Bumper \$ 300.00 200

Remove, refit and replaced damage lamps \$ 150.00 30
and check up rear electrical wiringRemove and refit inner garnishes trim to \$ 200.00 50
assist repair

To apply undercoating on replaced panel \$ 120.00 30

To Respray Painting. \$ 1,200.00 600

Panel Beating \$ 1,200.00 400

\$ 3,170.00**GRAND TOTAL**\$ 11,816.30P- 4314-24
N- 30
L- 1310
5 654-24L/S- 4523-39
= 4500**Survey:**

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name)

Steve (LKK)

(Contact)

8322 8813

(Email)

(Signature)

(Date/Time)

1/6/20, 2:30pm

WKL R

4 wks

L/S

My L by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: