Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)

Sent: Tuesday, 2 June 2020 11:50 am janicechou@alanutd.com

Cc: kennychan@alanutd.com; SUR; alanauto@gmail.com

Subject: SLS 4483X OD (ECICS) DOA - 28/05/2020

Dear Janice,

As instructed by our client, please proceed to repair the insured vehicle SLS 4483X (Excess \$ 0/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.