

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 07 Jul 2020

Preliminary Advice

Vehicle No	: SLS4483X	Accident Date	: 28/05/2020
Make	: MITSUBISHI LANCER	Policy No.	: MPC20P00007300
Assignment Date	: 30/05/2020	Excess	: S\$0.00
Date of Inspection	: 01/06/2020	Est. Duration of Repair	: 7 days
Inspection At	: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the n/s front & n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,650.50
Revised Amount	:S\$	6,234.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,234.60
Lump Sum Repair	:S\$	4,950.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	41,000.00
COE / PARF Rebate	:S\$	31,425.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,575.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :