



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO20003976/Qvf3e2-1

50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER SINGAPORE 048623

Date : 04-06-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLZ 7979B	Veh. Inspected	SMQ 2359J
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2001116/GPL	Excess (\$)	0.00
Assign From	GNOH PAU LOONG	Assign Date	01/06/2020

2. Vehicle Particulars & Condition

Make & Model	AUDI Q5	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WAUZZZ8R3AA043437	Colour	BLACK
Odometer	122637	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/45 R20	DUNLOP	6 mm
L/H Front Tyre	255/45 R20	DUNLOP	6 mm
R/H Rear Tyre	255/45 R20	DUNLOP	6 mm
L/H Rear Tyre	255/45 R20	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/03/2020	Inspection Date	13/03/2020
Survey held at	ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------