

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9354D

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

01 JUN 2020

AAD2005-071

Not Authoised

*Resurvey B4 paint
 @ 1789.68*

SHD 9354D

JTDKB3FU803079382

TOYOTA

PRIUS

28.5.2020

FCIL

11/3/2019

	PART
1	REAR BUMPER
1	REAR BUMPER RE-INFORCEMENT
1	REAR BUMPER TOWING COVER
1	GUARD, REAR BUMPER, CENTER
1	REAR BUMPER SIDE RETAINER LH
1	REAR BUMPER SIDE RETAINER RH
1	REAR TAILGATE
1	REAR TAILGATE OUTER GARNISH
1	REAR TAILGATE WEATHERSTRIP
1	PANEL SUB-ASSY, BODY LOWER BACK
1	TAILLAMP LOWER RH
1	TAILLAMP UPPER RH
1	REAR BUMPER SIDE RH
1	REAR BUMPER SIDE LH
1	TAILLAMP LOWER LH
1	TAILLAMP UPPER LH
1	COVER, DECK TRIM, REAR
1	COVER, FLOOR UNDER, NO 1
1	COVER, FLOOR UNDER, NO 2
1	COVER, REAR FLOOR

	LIST	
\$	<i>Bu</i>	442.60 ✓
\$	<i>R</i>	332.70 X
\$	<i>Sm</i>	15.40 X
\$	<i>Dollar</i>	576.30 ✓
\$	<i>Sm</i>	116.50
\$	<i>Sm</i>	117.70
\$	<i>R</i>	1,147.80
\$	<i>Sm</i>	925.60
\$	<i>Sm</i>	372.30 } X
\$	<i>Sm</i>	650.30
\$	<i>Sm</i>	502.00
\$	<i>Sm</i>	451.80
\$	<i>Sm</i>	123.70
\$	<i>Sm</i>	123.70
\$	<i>Car</i>	502.00 ✓
\$	<i>Sm</i>	443.30 X
\$	<i>Sm</i>	126.70 X
\$	<i>Sm</i>	175.10 X
\$	<i>Sm</i>	241.90 X
\$	<i>Sm</i>	229.90 X

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

1SET	PARKING AID
1SET	REAR BUMPER CLIP
1	REAR TAILGATE TOYOTA LOGO

\$	<i>Sm</i>	700.00 X
\$	<i>Sm</i>	69.00 ✓
\$	<i>Sm</i>	47.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9354D

1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>Nu</i>	52.90	X
1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>Nu</i>	53.50	X
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>Nu</i>	80.00	X
1	REAR TAILGATE STICKER '6555-3333'	\$	<i>Nu</i>	80.00	X
1	REAR BUMPER PROTECTOR	\$	<i>Nu</i>	120.00	<i>305Nu</i>
1	REAR WHEEL RIM	\$	<i>Sm</i>	1,879.40	} X
1	REAR TYRE 195/65/15	\$	<i>Sm</i>	350.00	
1	REAR WHEEL RIM COVER	\$	<i>Sm</i>	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	<i>Nu</i>	38.00	
1	REAR LH BUMPER RETAINER CLIP	\$	<i>Nu</i>	38.00	
1SET	TAILLAMP LOWER CLIP	\$	<i>Nu</i>	33.00	
1SET	TAILLAMP UPPER CLIP	\$	<i>Nu</i>	33.00	
1	Rear Licence Plate with Moulding	\$	<i>Nu</i>	100.00	
TOTAL		\$		3,885.30	

TOTAL PARTS	\$	9,598.28
--------------------	-----------	-----------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>Nu</i>	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>h</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>h</i>	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>h</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>h</i>	220.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	<i>200l</i>
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	<i>200l</i>

AAD2005-071

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9354D

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>h</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>h</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
TOTAL	\$	14,170.00	
Over All Total	\$	23,768.28	

(PART-BY-PART) Repair Days

20 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[-> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD9354D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 May 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C01343
Chassis No.:	JTDKB3FU803079382
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	11 Mar 2019
First Registration Date:	11 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Mar 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	10 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,420.00
COE Rebate Amount:	\$16,336.00
Total Rebate Amount:	\$27,021.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 May 2020

OK