

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35937

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0384/2020/NS
Date : 01-Jun-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Rasul

5 days - ok - jb - 8 Aug 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Stoupas Jeremy Constatntine
Address : 25 Cove Way
#15-18
Singapore 096209
Telephone : +(HP) 82231196
Type of Claim : Own Damage Claim
Policy No. : 2100510117-02
Vehicle No : **SLP 7744 P**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Jun-17
Engine No : DAX 005239
Chassis No : WAUZZZF3H2022456
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 08-May-20
Place of Accident : Along Road 1 Lower Delta Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7744 P

S/N	Nature of Jobs		Estimated Charges	Surveyor's commendatio
1	To remove, check and reinstall front wire harness for headlights. Horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,400.00	\$ 1,400.00
3	To dismantle and renew front bumper, rhs front fender, bonnet, and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. (Lock carrier replaced)	\$	6,000.00	\$ 2,500.00
4	To respray front bumper, front bumper lower spoiler, rhs front fender, bonnet and both front wheel arch trims.	\$	5,000.00	\$ 1,650.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 13,072.00	\$ 6,222.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7744 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,445.00	\$ 1,956.00
2	FRONT BUMPER FIXING PARTS	\$ 254.00	
3	FRONT BUMPER SECURING STRIP - RH	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 210.00	
5	FRONT BUMPER GRILLE - CENTRE	\$ 134.00	\$ 107.20
6	FRONT BUMPER FRONT SPOILER	\$ 709.00	\$ 567.20
7	FRONT BUMPER UNDERRUN BAR	\$ 447.00	\$ 303.20
8	FRONT BUMPER CLOSING ELEMENT	\$ 161.00	\$ 128.80
9	RADIATOR GRILLE	\$ 3,327.00	\$ 2,661.60
10	QUATTRO INSCRIPTION	\$ 90.00	\$ 72.00
11	STRIKER PLATE	\$ 230.00	\$ 184.00
12	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 537.00	\$ 429.60
13	FRONT BUMPER END CAP - RH	\$ 86.00	
14	FRONT PARKING AID SEAL RING	4 \$ 14.00	\$ 11.20
15	FRONT BUMPER CARRIER	\$ 857.00	\$ 685.60
16	FRONT BUMPER FOAM FILLER PIECE	\$ 269.00	\$ 215.20
17	FRONT BUMPER FOAM FILLER PIECE COVER	\$ 120.00	
18	FRONT BUMPER GUIDE SECTION - RH	\$ 36.00	
19	FRONT BUMPER BRACKET - RH	\$ 239.00	
20	CAUTION SIGN STICKER	NEC \$ 13.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 10,213.00	\$ 7,321.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7744 P

/I Parts Description	C/F	Damage Parts & Prices		Remarks
		S/Nett		
			\$	7,321.60
AIRCON STICKER	NEC	\$	18.00	
HORN - RH HIGH TONE		\$	184.00	
FRONT FENDER - RH		\$	1,344.00	
FRONT FENDER ATTACHMENT PARTS		\$	62.00	
FRONT FENDER BRACE - RH		\$	212.00	
FRONT FENDER BRACKET - RH		\$	17.00	
BONNET		\$	3,824.00	\$ 3,059.20
BONNET ATTACHMENT PARTS		\$	133.00	
BONNET LIF HINGE - LH / RH	2	\$	304.00	
BONNET STRIKER - LH / RH	2	\$	226.00	
BONNET SOUND ABSORBER		\$	299.00	
BONNET IMPACT PROTECTION - LH / RH / C	3	\$	78.00	\$ 62.40
BONNET LID LOCK	2	\$	403.00	
BONNET RELEASE ELEMENT		\$	54.00	
BONNET BOWDEN CABLE - CENTRE		\$	54.00	
BONNET RELEASE ELEVER		\$	13.00	
LED HEADLIGHT - RH		\$	7,462.00	
LIFT CYLINDER - RH		\$	132.00	
LIFT CYLINDER HOSE		\$	118.00	
WHEEL HOUSING LINER - RH		\$	248.00	
SUB TOTAL SPARE PARTS CHARGE :		\$	15,185.00	\$ 10,443.20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7744 P

S/N Parts Description		Damage Parts & Prices	
		S/Nett	Remarks
	C/F		\$ 10,443.20
41 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 36.00	
42 WHEEL SPOILER		\$ 146.00	
43 FRONT WHEEL COVER - LH / RH	2	\$ 1,190.00	\$ 952.00
44 HEADLIGHT MOUNTING - RH		\$ 112.00	\$ 89.60
45 LOCK CARRIER		\$ 1,206.00	\$ 964.80
46 AIRCON CONDENSER		\$ 566.00	
47 RADIATOR		\$ 838.00	
48 RADIATOR FAN RING		\$ 389.00	
49 RADIATOR FAN		\$ 2,226.00	
50 RADIATOR AIR GUIDE - UPPER		\$ 45.00	
51 RADIATOR AIR GUIDE - CENTRE		\$ 40.00	\$ 32.00
52 RADIATOR AIR GUIDE - LH / RH	2	\$ 106.00	\$ 84.80
53 RADIATOR LOUVRE		\$ 504.00	
54 SERVOMOTOR		\$ 172.00	
55 CHARGE AIR COOLER		\$ 746.00	
56 CHARGE AIR COOLER SEAL RING	2	\$ 84.00	
57 TEMPERATURE SENSOR BRACKET		\$ 15.00	
58 FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
SUPPLEMENTARY		\$ 200.00	\$ 160.00
59 SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS CHARGES	:	\$ 34,479.00	\$ 12,786.40
TOTAL LABOUR CHARGES	:	\$ 13,072.00	\$ 6,222.00
GRAND TOTAL	:	\$ 47,551.00	\$ 19,008.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0384/2020/NS 22-Jun-20 Glory Tan 1 of 1 SLP 7744 P Audi Q5 2.0 TFSI qu	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Headlamp mounting LHS	\$ 112.00	\$	89.60
2	Mix coolant for radiator	\$ 88.00	\$	70.40
TOTAL		\$ 200.00	\$	160.00

For Premium Automobiles Pte Ltd

Authorised Signature