

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 04 Jun 2020

Preliminary Advice

Insured Vehicle No : SLV9169E
TP Vehicle No : SLJ1375S
Make : NISSAN QASHQAI
Date of Inspection : 03/06/2020
Inspection At : My Car Consultant Pte Ltd (Ubi)
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Accident Date : 26/05/2020
Assignment Date : 02/06/2020
Est. Duration of Repair : 5 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s & o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,010.68
Revised Amount	:S\$	6,377.78
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,377.78

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP