



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

Vehicle:

Make / Model:

Chassis No:

ML PK
3/6/20, 4. 90pm

L/S, My AL sy
2/6/2020

SMN76365

TOYOTA PRIUS 3 dys

Steve (LKK)

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / DEF	1	\$ 610.40	\$ 610.40
2	REAR BUMPER SIDE RETAINER LH / DR	1	\$ 113.60	\$ 113.60
3	REAR BUMPER SIDE RETAINER RH / DR	1	\$ 113.60	\$ 113.60
4	REAR BUMPER REINFORCEMENT / X NM	1	\$ 310.50	\$ 310.50
5	REAR BUMPER BRACKET LH / NM	1	\$ 115.30	\$ 115.30
6	REAR BUMPER BRACKET RH / NM	1	\$ 115.30	\$ 115.30
7	REAR BUMPER BRACKET RH / NM	1	\$ 718.50	\$ 718.50
8	REAR BUMPER LIP / NM	1	\$ 80.60	\$ 80.60
9	REAR BUMPER REFLECTOR LH / NM	1	\$ 80.60	\$ 80.60
10	REAR BUMPER REFLECTOR RH / NM	1	\$ 660.20	\$ 660.20
11	REAR END PANEL / X R	1	\$ 225.10	\$ 225.10
12	REAR END PANEL TOP GARNISH / X NM	1	\$ 169.50	\$ 169.50
13	REAR KEYLESS SENSOR / X NM	1	\$ 438.60	\$ 438.60
13	REAR KEYLESS SENSOR WIRE HARNESS / X NM	1	\$ 438.60	\$ 438.60
Less 25%				\$ 3,751.80
Total				\$ 937.95
				\$ 2,813.85
S/Nett items:				
1	REAR REVERSE SENSOR / Short	1 SET	\$ 250.00	\$ 250.00
2	REAR REVERSE CAMERA / X NM	1 SET	\$ 300.00	\$ 300.00
3	REAR BUMPER CLIP / NM	1 SET	\$ 80.00	\$ 80.00
4	REAR END PANEL GARNISH CLIP / X NM	1 SET	\$ 30.00	\$ 30.00
5	FLOOR PANEL SEALANT / X NM	1	\$ 50.00	\$ 50.00
6	END PANEL SEALANT / X NM	1	\$ 50.00	\$ 50.00
7	MISCELLANEOUS / X NM	1	\$ 200.00	\$ 200.00
				\$ 960.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00
4	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
5	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
6	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
				\$ 1,650.00

523.90

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

1469-60
- 25%
1102.20

200

30

30

30

30

30

30

30

30

30

30

30

30

30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts Replacement Amount

\$ 3,773.85

Total Amount for Labour

\$ 1,650.00

Total Amount

\$ 5,423.85

P- 1102-20
N- 230
L- 790
2122-20

L/S- 1697-76
= 1700

790