



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
Tel : 6484 1221 Fax : 6484 7829
385 Sin Ming Drive (Inside Vitom) Singapore 575718.
Tel : 6753 2112 Fax : 6451 0394
Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Your Ref : SH 9462 Z

Our Ref : CIV1303467 / SLT 3467 T

Date : 04.08.2020

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street

#04/05 10B Building

Singapore 049711

RE : ACCIDENT INVOLVING **SLT 3476 T & SH 9462 Z**
ACCIDENT DATE **02.06.2020**
ACCIDENT ALONG **TAMPINES CENTRAL 4**

We are the workshop for the owner of motor vehicle no : **SLT 3476 T** which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured **SH 9462 Z** we are submitting these claims for your consideration.

1	Cost of repair	S \$	3,690.31
2	Loss of rental <u>5</u> days @ \$ 71.95 / day	S \$	359.75
<div style="border: 1px solid black; padding: 5px;"><p>DOA : 02.06.2020 PRI Request : 03.06.2020 @ 11:15 Survey Date : 25.06.2020 @ 10:15 to arrange PRI Recommend : 5 days Weekend : Total : 5 days</p></div>			
5	LTA Fee	S \$	7.45
		S \$	4,057.51

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim
Claims Executive
Email : carmen@esteemperf.com.sg



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04/05 10B Building
Singapore 049711

ATTN: Motor Claim Department

Your Ref No: SH9462Z
Claim Type: Third Party
Accident Date: 02/06/2020
TP Veh Reg No: SH9462Z

Claim No: CER1302621
Final No: CIV1303467
Date: 04 Aug 2020
Policy No:
Veh Reg No: SLT3476T
Make/Model: TOYOTA PRIUS
HYBRID 1.8 CVT
Chassis No: JTDKB3FU103574801
Engine No: 2ZRS106527
Reg. Date: 26/10/2017

Tax Invoice to Vehicle No :SLT3476T

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Others			
1 COST OF REPAIR	1 PCS	3,448.89	
		3,448.89	3,448.89
Total			S\$ 3,448.89
Add GST @ 7%			241.42
Total Amount Payable			<u>S\$ 3,690.31</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED NINETY AND CENTS THIRTY ONE ONLY

The above vehicle was surveyed by KENNETH on 25/06/2020

For Esteem Performance Pte Ltd

E. & O. E.



AUTHORISED SIGNATURE

CONFIDENTIAL



Grab Rentals Pte Ltd
201617200G
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Date of Accident: 02.06.2020	Time: 15:20
Accident Location: TAMPINES CENTRAL 4	

Rental information of the accident vehicle

Registered Owner:	Grab Rentals Pte Ltd
Vehicle Number:	SLT3476T
Hirer Name:	TAY TUAN BIAN
Hirer NRIC last 4 Digit: (XXXXB)	504Z
Rental Rate: (inclusive GST)	\$71.95

Details of repair

Date in:	20.07.2020 @ 09:00
Date out:	24.07.2020 @ 16:45

We hereby authorize our appoint workshop, **Esteem Performance Pte Ltd** to handle any settlement of claims and receiving settlement payments in respect of the said accident.



Grab Rentals – Accident Team

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 05 Aug 2020 / 09:20:23

Receipt Date/Time : 05 Aug 2020 / 09:20:22

Tax Invoice/Receipt

Receipt No. : ITNET-00000-200805-000410

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Result of Insurance Enquiry - SH9462Z				
As at 02 Jun 2020/15:20:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SH9462Z Enquiry Fee 20200805091923039409	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	512972XXXXXX5823	eNETS Credit Card		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

LETTER OF AUTHORITY

To Whom It May Concern:

ACCIDENT INVOLVING SLI 3476T & SH9462Z along Tampines Central 4
On 02/06/2020 @ 15:20

I, Grab Rentals Pte Ltd Nric No. 201617200G
of 18 Sin Ming Lane #01-08 Midview City Singapore 573960
Owner of motor vehicle no. SLI 3476T do hereby appoint M/S
ESTEEM PERFORMANCE PTE LTD as my authorized representation and
as my solicitors to write, to negotiate and settle my claim against
the other party/parties involved in the above mentioned accident. M/S ESTEEM
PERFORMANCE PTE LTD shall have absolute discretion to settle the matter at the best
terms.

I also confirm and instruct that any agreed settlement sum in respect of my claim be paid to
M/S ESTEEM PERFORMANCE PTE LTD and such payment will constitute a full and final
discharge of my claims.

I further authorize M/S ESTEEM PERFORMANCE PTE LTD to execute the discharge
voucher on my behalf.

Signature of Owner

