

Estimate

04/06/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SMH7660C

Veh Model :- TOYOTA HARRIER

Estimate# :- CK420699

Claim # :- *TP1 CK138322*

ACC. Date :- 30/05/02

Terms :- C.O.D Days

Remarks :- *MFR 06 JAN 2016 (2015)*

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER <i>cm /</i>	1 PC	1,490.00	1,490.00
2.	REAR BUMPER LOWER <i>de /</i>	1 PC	455.00	455.00
3.	REAR BUMPER CLIPS <i>res -</i>	10 PC	5.00	50.00
4.	REAR BUMPER SPONGE <i>cm /</i>	1 PC	140.00	140.00
5.	END PANEL - REPAIR	1 PC		
LIST TOTAL S\$				2,135.00
25% DISCOUNT S\$				-533.75
				1,601.25
LABOUR :				
TO REMOVE & TRANSFER REAR PARKING SENSOR & DIAGNOSE FUNCTION				<i>40</i> 60.00
TO REPAIR ON <i>tailgate</i> END PANEL. TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION				<i>300</i> 400.00
TO SPRAY PAINT ON REPAIRED AREA				<i>400</i> 200 400.00
LABOUR TOTAL S\$				860.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,461.25

GST @ 7 % 172.29

AMOUNT DUE S\$ 2,633.54

Customer's Signature/Co Stamp MOVA AUTOMOTIVE PTE LTD

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
3 days
4/5
15/06/2020 @ 1140
Resurvey after repair