

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20006164/Dea3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	26/05/2022	
	ATTN:VALE OH			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKD 2638X	Veh. Inspected	ł	FBR 3732H	
	Policy No.	GA127852	Coverage (\$)		0.00	
	Claim No.	S0M02P3H	Excess (\$)		0.00	
	Assign From		Assign Date		11/06/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA NMAX155	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3SG431000013390	Colour		WHITE / BLACK	
	Odometer	1779 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/70 R13	DUNLOP		3 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	130/70 R13	DUNLOP		3 mm	
	L/H Rear Tyre				mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/06/2020	Inspection Dat	e	12/06/2020	
	Survey held at	S 9 MOTOR TRADING PTE LTD				
		BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				
		·				