

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Withheld
Presurvey B4point
5112.60 5 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: _____ Third Party

Date: 09.06.2020

Accident Date : 24.05.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Hiace" Reg. No. GBJ5511H Claiming Against Your Insured Reg. No. SMM3663U		
1pc	Tailgate <i>Br</i>		2,162.00
1pc	Tailgate Emblem <i>nu</i>		81.00
1pc	Tailgate Sticker Toyota <i>nu</i>		49.60
1pc	Tailgate Sticker Hiace <i>nu</i>		49.60
1pc	Tailgate Lock <i>ed</i>		286.00
15pc	Tailgate Trim Board Clips <i>nu</i>		109.20
1pc	Tailgate Weatherstrip <i>su x</i>	7.28	476.00
1pc	Tailgate Weatherstrip Top Protective Plate <i>ed</i>		390.00
1pc	Rear Bumper <i>Br</i>		435.00
1pc	Rear Bumper Bracket <i>nu</i>		38.60
10pcs	Rear Bumper Clips <i>nu</i>	5.78	57.80
1pc	End Panel <i>2</i>		522.00
	Less 25%		4,656.80
			1,164.20
			3,492.60
	Tailgate Glass Sealant		50.00 SN
	Tailgate Glass Sealer		40.00 SN
	Tailgate Glass Fastener		50.00 SN
	Tailgate Sticker 70km		18.00 SN/2
	Tailgate Sticker		50.00 SN
	Tailgate Lower Protector		135.00 SN
	Rear Bumper Reverse Sensor		280.00 SN
	Rear Number Plate		45.00 SN
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring etc		120.00 50/
	To Dismantle / Transfer Tailgate Fittings / Ancillary Accessories		120.00 60/
	To Dismantle / Refit Tailgate Glass To Facilitate Repair		160.00 120/
	To Supply End Panel Body Sealant		60.00 7 30
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel Joint Sealant		120.00 7 60
	Labour Charge - Panel Beating, Repairing Of Rear Floor Plate, End Inner Panel, Cnt Weld End Panel and Parts Replacement		950.00 7 600
	To Respray Affected Areas		800.00 600/
			800.00
			2,998.00
		Total :	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

nu 40SN 50.00 SN
nu 20SN 40.00 SN
nu 30SN 50.00 SN
nu 18.00 SN/2
nu 50.00 SN
nu 135.00 SN
Short 280SN 280.00 SN
By 25SN 45.00 SN