

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006190/URA3Q2
Date: 10/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800035810
Claimant Vehicle No :	FBE5248U	Insured Vehicle No :	SMA1001G
Date of Loss:	20/05/2020	Nature of Claim:	TP
		Claim No:	7134806915SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE5248U	Engine No:	5YP302392
Make & Model:	YAMAHA T135, 135cc	Chassis No:	5YP302392
Reg. Date:	14/05/2010 (Man. Year: 2010)	Odometer:	4234 km
Colour:	Black		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	80-90-17
Front Left Side:	Leopard 6 mm	Rear Left Side:	Leopard 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,092.40	828.30	2,264.10	73.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	200.00	660.00	76.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,952.40	1,028.30	2,924.10	73.98
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	3,952.40	800.00	3,152.40	79.76
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
	Nett Liability (S\$)	880.00		

INSPECTION

Date of Assignment:	11/06/2020		
Date Inspected:	16/06/2020	Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: Jaslin Kok Chin Yi

4/10/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Serviceable	640.00 FL	*- FL
2	1		*FRONT WHEEL RIM	Not Necessary	380.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
5	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
6	1		*HANDLE BAR	Not Necessary	88.00 FL	*- FL
7	1		*SET HAND GRIP	Not Necessary	55.00 FL	*- FL
8	1		*SIDE MIRROR	Cut	55.00 FL	*55.00 FL
9	1		*CLUTCH LEVER	Cut	32.00 FL	*32.00 FL
10	1		*SET FAIRING ASSY	Cracked / Cut	525.00 FL	*525.00 FL
11	1		*FRONT FOOTREST BRACKET	Bent	65.00 FL	*65.00 FL
12	2		*FRONT FOOTREST RUBBERS	Torn	70.00 FL	*70.00 FL
13	1		*GEAR PEDAL	Serviceable	42.00 FL	*- FL
14	2		*REAR FOOTREST BRACKETS	Not Necessary	156.00 FL	*- FL
15	1		*REAR FOOTRESTS	N/S Cut	80.00 FL	*40.00 FL
16	1		*SIDE STAND	Repair	75.00 FL	*- FL
17	1		*MAIN STAND	Repair	95.00 FL	*- FL
18	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
19	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
20	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
21	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
22	1		*BASKET	Not Necessary	50.00 FS	*- FS
23	1		*REAR BOX	Cut	120.00 FS	*120.00 FS
24	1		*E.R.P IU	Not Necessary	175.00 FS	*- FS
25	1		*FRONT TYRE	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,355.00	907.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	262.60	78.70
Total Parts (\$\$)	3,092.40	828.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	350.00	0.00
4	TO PROVIDE LABOUR	New	380.00	200.00
Gross Labour Cost (\$\$)			860.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >