GBA 6589A

PARTS				S/N		LABOUR		SUPP (PARTS)		
	\$1,942.10	\$0.00	\$0.00		\$134.00		\$30.00		\$0.00	
	\$81.00	\$0.00	\$0.00		\$60.00		\$60.00		\$0.00	
	\$149.00	\$0.00	\$0.00		\$40.00		\$120.00		\$0.00	
	\$286.00	\$0.00	\$0.00		\$30.00		\$50.00		\$0.00	
	\$98.00	\$0.00	\$0.00		\$12.00		\$30.00		\$0.00	
	\$198.00	\$0.00	\$0.00		\$12.00		\$90.00		\$0.00	
	\$536.00	\$0.00	\$0.00		\$60.00		\$1,000.00		\$0.00	
	\$192.00	\$0.00	\$0.00		\$50.00		\$900.00		\$0.00	
	\$57.80	\$0.00	\$0.00		\$200.00		\$0.00		\$0.00	
	\$38.60	\$0.00	\$0.00		\$120.00		\$0.00		0%	
	\$78.00	\$0.00	\$0.00		\$20.00		\$0.00		<u>\$0.00</u>	
	\$466.82	\$0.00	\$0.00		\$20.00		\$0.00	SUPP (SN)		
	\$856.62	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
ĺ	\$81.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$496.80	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$510.20	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$57.80	\$0.00	\$0.00		\$758.00		\$2,280.00		<u>\$0.00</u>	
	\$304.42	\$0.00	\$0.00							
	\$145.50	\$0.00	\$0.00					SUPP(LABOUR)		
1488.0	0 \$744.00	\$0.00	\$0.00	1		TOTAL			\$0.00	
	\$152.00	\$0.00	\$0.00			6,161.7	5 \$5 ,603.75		\$0.00	
	\$0.00	\$0.00	\$0.00			,	\$758.00		\$0.00	
	\$0.00	\$0.00	\$0.00				\$2,280.00		<u>\$0.00</u>	
	\$0.00	\$0.00	\$0.00			SUPP	\$0.00	TOTAL SUPP	<u>\$0.00</u>	
	\$0.00	\$0.00	\$0.00			P/P 9,199	.75 \$8,641.75	MAKE / MODEL	TOYOTA HIACE (2982cc)	
	\$0.00	\$0.00	\$0.00			9,199.75	\$ 8,641.7 5	MARKET VALUE	\$0.00	
	\$0.00	\$0.00	\$0.00				80%	LTA REBATE	\$0.00	
	\$0.00	\$0.00	\$7 ,471.66	4	5.66	7,359.80	\$ 6,913.4 0	NETT VALUE	\$0.00	
	\$0.00	\$0.00		1		L/S	\$7,000.00	RED	\$12,035.70	63
	\$0.00	\$0.00	\$7 ,471.66	8.21				TOTAL TP EST	\$19,035.70	
	\$0.00	\$0.00	75%	1				REPAIR DAYS	9	
	\$0.00	\$0.00			1 75			REMARKS	=	