

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cecilia Low Date: 16 Jun 2020

**Preliminary Advice**

Insured Vehicle No	:	SJP73L		
TP Vehicle No	:	SLH1632K	Accident Date	: 12/06/2020
Make	:	NISSAN SYLPHY	Assignment Date	: 15/06/2020
Date of Inspection	:	15/06/2020	Est. Duration of Repair	: 6.00
Inspection At	:	AUTOLUTION INDUSTRIAL PTE LTD (HQ) 19 UBI ROAD 4 SINGAPORE 408623		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:	S\$ 13,530.18
Revised Amount	:	S\$ 5,337.92
Check Items (Estimated)	:	S\$ 5,518.74
Total	:	S\$ 10,856.66
Lump Sum Repair		:

**Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :